

REPORT of SURVEY for REPAIRS, &c.

No. 4375

No. in Survey held at Reg. Book.

Leith

Date, first Survey 6th May

Last Survey 23rd June 1880

on the

Sew Sch^r "Ella"

Master George Milkie

TONNAGE under Tonnage Deck

469

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

693

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St^rmer, cut on Bm.

443

Built at

Inverkeithing

When built

1870

10

Owners

J. Cormack

Port belonging to

Leith

Residence

4 Bernard Street, Leith

By whom built

Scott

Destined Voyage

Riga

If Surveyed Afloat or in Dry Dock

(State Name of Dock)

Hawthorn's Wharf

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

4232

Port Leith

Classed S. S. 2-79

90 A. 1.

REPAIRS, OR EXAMINATION AS PER RULE

Renewal of Boiler &c

Load line 11 ft 7 in

5.79

Cause of Repairs to be clearly stated.

All oxidation removed from floors under the Boiler: the rider plate much wasted & 8 ft now renewed: Cement under Boilers & at other parts of the Vessel where found defective now renewed. Coal bunkers repaired. A large portion of the close caking removed: the whole in the deep midship tank renewed of 3" pitch pine: in fore hold about $\frac{1}{2}$ & several planks in main hold renewed of 2 $\frac{1}{2}$ pp. Engine & Boiler casing above hatchway Comings renewed also the roof of 5 $\frac{1}{2}$ iron respectively & the whole efficiently stiffened with angle irons: Several shifts of deck flat over boiler renewed of pitch pine & the whole recaulked. The Vessel painted inside with red lead.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

General Observations, Opinion as to Class, &c.

Greenails, Nuts

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper (or Lead) Cement

When put on 1870

Caulking of

Bottom, Deck, & Waterways

Scuppers

Cargo and Main Hatchways

Hatches

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Is now in good & efficient condition in my opinion eligible to remain as classed

The Amount of Entry Fee

£ 3 : 3 : 0

received by me,

11th Aug^r 1880.

Certificate (if required)

to be sent as per margin

Travelling Expenses (if any)

Committee's Minute

Friday, August 13th 1880

Character assigned

Lloyd's M.C.B. 80

NB 80

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON 494-0302

ROBT. EDMD. TAYLOR & SON, Commercial Steam Printers, 19, Old Street Goswell Road, London.