


ANNUAL SURVEYS.

*27504

(Received at London Office, 1st 8, 80)

No. 29515 Survey held at London Date, first Survey 12th August Last Survey 12th August 1880
 No. in on the Iron Ste. Fr. "Falcon" Master T. Woodward
 Reg. Book. 57 Tonnage 389 Built at Newcastle When built 1876-1 mo.
 By whom built Mitchell Owners Gen. Steam Nav. Co.
 Port belonging to London Destined Voyage Antwerp.
 If Surveyed Afloat or in Dry Dock On the Gridiron of Gen. Steam Nav. Co.



Last Survey, No. 26570 Port of London Classed S. S. Lon. N-1-80 Years assigned. 100 A. 1 Character in Register Book. 4.80

Present Condition of the Decks <u>good</u>	Treenails <u>rivets</u> <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>D^o</u>	Breasthooks and Stemson <u>D^o</u>	Pumps <u>D^o</u>
Comings <u>D^o</u>	Transoms, Pointers , and Crutches <u>D^o</u>	Boats <u>D^o</u>
Upper Deck Beams & Fastenings <u>D^o</u>	Timbers of the Frame at the Openings <u>D^o</u>	Masts, Yards, &c. <u>D^o</u>
Lower Deck Beams & Fastenings <u>D^o</u>	Ditto ditto at other places <u>D^o</u>	Condition, how ascertained <u>from the deck</u>
Planksheers <u>D^o</u>	Keelsons <u>D^o</u>	Sails <u>good</u>
Sheerstrakes <u>D^o</u>	Clamps and Shelves <u>D^o</u>	Anchors, No. of <u>3 B. 1 S. 2 K.</u>
Topsides <u>D^o</u>	Ceiling <u>D^o</u>	Cables <u>complete</u>
Wales <u>D^o</u>	Rudder <u>D^o</u>	Hawsers and Warps <u>sufficient</u>
Planking (Bottom) and Counter <u>D^o</u>	Copper or Y.M. <u>When put on</u>	Standing and Running Rigging <u>D^o</u>
Engine Room Skylights <u>good</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	
Coal Bunker, Openings, Lids, &c. <u>good</u>	Scuppers <u>good</u>	Cargo and Main Hatchways <u>good</u>
Hatches <u>good</u>		

General Observations, Opinion as to Class, &c.
The bottom has been examined, cleaned and coated.
This vessel appears to be eligible to remain as classed.

Committee's Minute Friday, August 20th 1880
 Character assigned 100 A. 1
 Surveyor to Lloyd's Register of British and Foreign Shipping. J. H. Truscott
 Certificate (if required) 18 Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Planking (Bottom) and Counter _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. <u>When put on</u> _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Cargo and Main Hatchways _____
Hatches _____		

General Observations, Opinion as to Class, &c.
 Committee's Minute 18
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required) _____ Paid _____ 18____

IRON 494-0310

