

ANNUAL SURVEYS.

27555
(Received at London Office, 27 7 80)

No. 29530 Survey held at London Date, first Survey 23 June Last Survey 28 June 1880
 No. in on the S.S. Virginia Schilizzi Master Tucker
 Reg. Book. 323 Tonnage 821 Built at S. Shields When built 1872-11
 By whom built Redhead Owners H. A. Clarkson &
 Port belonging to London Destined Voyage Constradt
 If Surveyed Afloat or in Dry Dock Bridge dry dock

Last Survey, No. 100 Port of London Classed 100 A 3.80
 Character in Register Book. S.S. 2-1.77.
 Present Condition of the Decks Good
 Waterways de Treenails de Breasthooks and Stemson de Windlass and Capstan Good
 Comings de Transoms, Pointers, and Crutches de Pumps two de
 Upper Deck Beams & Fastenings de Timbers of the Frame at the Openings de Boats de
 Lower Deck Beams & Fastenings de Ditto ditto at other places de Masts, Yards, &c. de
 Planksheers de Keelsons de Condition, how ascertained from deck
 Sheerstrakes de Clamps and Shelves de Sails well found
 Topsides de Ceiling de Anchors, No. of 3 B. 1 S & Keegls
 Wales de Rudder de Cables complete
 Plank (Bottom) and Counter de Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways de Hauers and Warps sufficient
 Engine Room Skylights de Coal Bunker, Openings, Lids, &c. de Scuppers de Standing and Running Rigging for
 Cargo and Main Hatchways de Hatches de
 General Observations, Opinion as to Class, &c. The bottom cleaned and recoated.


This vessel appears eligible to remain as classed.
Querred on the particulars relating to water ballast tanks.
The. London
R. Williamson

Committee's Minute Tuesday, August 2nd 1880.
 Character assigned 100
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Character in Register Book. _____
 Present Condition of the Decks _____
 Waterways _____ Treenails _____ Breasthooks and Stemson _____ Windlass and Capstan _____
 Comings _____ Transoms, Pointers, and Crutches _____ Pumps _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Boats _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Masts, Yards, &c. _____
 Planksheers _____ Keelsons _____ Condition, how ascertained _____
 Sheerstrakes _____ Clamps and Shelves _____ Sails _____
 Topsides _____ Ceiling _____ Anchors, No. of _____
 Wales _____ Rudder _____ Cables _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____ Hauers and Warps _____
 Caulking of Bottom, Deck, & Waterways _____ Standing and Running Rigging _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18____



Konrad Schütz



© 2019

Lloyd's Register
Foundation