

No. 29519 Survey held at London Date, first Survey Aug 4th Last Survey Aug 11th 1880
 No. in on the S Roman Empire Master J Adams
 Reg. Book. 492 Tonnage 1542 Built at N Hartlepool When built 1866-1870 24582
 By whom built Pole Owners G Duncan
 Port belonging to London Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St

Last Survey, No. 24245 Port of Iron Classed A 7 8.75
 Years assigned. 55 Character in Register Book. SS Linn 28-79.

Present Condition of the Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Condition, how ascertained	<u>From St</u>
Planksheers	"	Keelsons	"	Sails	<u>Good</u>
Sheerstrakes	"	Clamps and Shelves	"	Anchors, No. of <u>3 Bns. St J Redg.</u>	
Topsides	"	Ceiling	"	Cables <u>Part on St</u>	<u>Good</u>
Wales	"	Rudder	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>Now</u>		Standing and Running Rigging	"
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.		Scuppers	<u>Good</u>	Hatches	"

General Observations, Opinion as to Class, &c. Bottom ke coated.
She is now in good condition and eligible to remain as classed.

Committee's Minute: 20th Aug^t 1880
 Character assigned A 1
 Surveyor Samhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid