

ANNUAL SURVEYS.

No. 34510 Survey held at London Date, first Survey July 25 Last Survey Aug 27 1880
 No. in on the S Ben Meris Master Mackie
 Reg. Book. 290 Tonnage 1061 Built at Glasgow When built 1868 - 6
 By whom built Barclay Owners Natson Bros
 Port belonging to Glasgow Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Greens Dry Dock & afloat

Last Survey, No. 24510 Port of Iron
 Present Condition of the
 Decks Good Treenails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. " When put on "
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. "

Years assigned. 8.75 Character in Register Book. SS Lin No 2-77
 Classed A1

She is now in good condition and eligible to remain as classed.
The Committee have allowed this vessel to make her present voyage & then to be placed under Special Survey.
Secretary letter to Owners dated 27 July 1880.

Committee's Minute Friday, September 3rd, 1880

Character assigned A1

Senhouse Martindale

T.B.W. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) " Paid " 18 "

No. 216 Survey held at London Date, first Survey July 23 Last Survey Aug 21 1880
 No. in on the BK Promsides Master J. Spencer
 Reg. Book. 216 Tonnage 895 Built at Sunderland When built 1861 - 4
 By whom built Aswold Owners Temperleys Carter & Carter
 Port belonging to London Destined Voyage Algon Bay
 If Surveyed Afloat or in Dry Dock Greens Dry Dock & afloat

Last Survey, No. 24149 Port of Iron
 Present Condition of the
 Decks Good Treenails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. " When put on "
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. "

Years assigned. 4.75 Character in Register Book. SS Lin No 3-76
 Classed A1

She is now in good condition and eligible to remain as classed

Committee's Minute Friday, September 3rd, 1880

Character assigned A1

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) " Paid " 18 "