

# ANNUAL SURVEYS.

27596

No. 34510 Survey held at London Date, first Survey July 25 Last Survey Aug 27 1880  
 on the S Ben Meris Master Mackie  
 Reg. Book. 290 Tonnage 1061 Built at Glasgow When built 1868 - 6  
 By whom built Barclay Owners Natson Bros  
 Port belonging to Glasgow Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Greens Dry Dock & afloat

Last Survey, No. 24510 Port of Iron  
 Present Condition of the  
 Decks Good Treenails Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. " When put on "  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. "

Years assigned. 8.75 Character in Register Book. Classed A1  
SS Lin No 277

*She is now in good condition and eligible to remain as classed.*  
*The Committee have allowed this vessel to make her present voyage & then to be placed under Special Survey.*  
*Secretary letter to Owners dated 27 July 1880.*

Committee's Minute Friday, September 3rd, 1880  
 Character assigned A1 Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) " Paid " 18 "

No. 216 Survey held at London Date, first Survey July 23 Last Survey Aug 21 1880  
 on the BK Promsides Master J. Spencer  
 Reg. Book. 216 Tonnage 895 Built at Sunderland When built 1861 - 4  
 By whom built Aswold Owners Temperleys Carter & Carter  
 Port belonging to London Destined Voyage Algon Bay  
 If Surveyed Afloat or in Dry Dock Greens Dry Dock & afloat

Last Survey, No. 24149 Port of Iron  
 Present Condition of the  
 Decks Good Treenails Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. " When put on "  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. "

Years assigned. 4.75 Character in Register Book. Classed A1  
SS Lin No 376

*She is now in good condition and eligible to remain as classed*

Committee's Minute Friday, September 3rd, 1880  
 Character assigned A1 Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) " Paid " 18 "