

# ANNUAL SURVEYS.

No. 4919 Survey held at Hull Date, first Survey 24 Sept. Last Survey 4 Sept. 1880  
 No. in Reg. Book. 4919 on the Ron Lw. St. Empress Master N. Northard  
 Tonnage 1080 Built at Hull When built 1868 4 mo  
 By whom built Garre Owners N. Sigdell  
 Port belonging to Hull Destined Voyage Hamburg  
 If Surveyed Afloat or in Dry Dock Afloat in Pinner dock

Last Survey, No. 24323 Port of Iron Classed U.P. 7.48 Years assigned. 8.49 Character in Register Book. A. 1.  
 Present Condition of the Decks Good Treacants Good  
 Waterways do Breasthooks and Stenson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Kelsons do Clamps and Shelves do  
 Sheers do Ceiling do  
 Sheerstrakes do Rudder do  
 Topsides do Copper or Y.M. do When put on do  
 Wales do Caulking of Bottom, Deck, & Waterways Good  
 Plank (Bottom) and Counter Good Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. 4/1

*This vessel appears to be in good condition, and is eligible in my opinion to remain as Classed*

Committee's Minute Tuesday, September, 21st 1880.

Character assigned A. 1.

*James M. Neil*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) 18

No. 4919 Survey held at Hull Date, first Survey 24 Sept. Last Survey 4 Sept. 1880  
 No. in Reg. Book. 4919 on the Ron Lw. St. Mona Master N. Bromley  
 Tonnage 125 Built at Hull When built 1866 4 mo  
 By whom built Garre Owners N. Bailey  
 Port belonging to Hull Destined Voyage Wattie  
 If Surveyed Afloat or in Dry Dock On Slip-way and afloat

Last Survey, No. 24915 Port of Iron Classed U.P. 7.48 Years assigned. 10.49 Character in Register Book. A. 1.  
 Present Condition of the Decks Good Treacants Good  
 Waterways do Breasthooks and Stenson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Kelsons do Clamps and Shelves do  
 Sheers do Ceiling do  
 Sheerstrakes do Rudder do  
 Topsides do Copper or Y.M. do When put on do  
 Plank (Bottom) and Counter do Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. 4/1

*Placed on blocks on Slip-way & the bottom painted. It is in good condition and eligible in my opinion to remain as Classed*

Committee's Minute Tuesday, September, 21st 1880.

Character assigned A. 1.

*James M. Neil*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) 18