

ANNUAL SURVEYS.

27627

Re: 27/8/80

No. 238 040. Survey held at Antwerp Date 18 - 21 September 1880.
 on the S.S. Hector Master Schank Last
 Tonnage 1534 Built at Sunderland When built 1863 - 4 m
 By whom built Laing Owners E. P. Gouley
 Port belonging to Sunderland Destined Voyage Antwerp - New Orleans
 If Surveyed Afloat or in Dry Dock in dry dock.

Last Survey, No. 2720 Port of Iron Classed 90A.2.

The present Condition of the

Decks	good	Treenails	Nivets	good	Windlass and Capstan	good
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors No. of 0	"
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	"
Wales	"	Rudder	"	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper	Paint	When put on 1880		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Placed in dry dock and examined at Gouley's request on account of damages to Propeller and other small damages to Figure Head, Rail & E. and W. masts, mentioning and found the ship where seen, in a good & seaworthy condition. Replaced Propeller by a new one, repaired small damages and repainted bottom.

Committee's Minute Tuesday, September, 28th 1880.

Character assigned

90A

JBW certificate

Certificate (if required) yes.

No. Survey held at Date 18
 on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute 18

Character assigned

IRON 494-0469



© 2019

Lloyd's Register

Certificate (if required)