

ANNUAL SURVEYS.

24650

Rec 4/10/80

No. in Reg. Book. **No. 35** Survey held at **Kathenbury** Date, first Survey **26 of June** Last Survey **1st of September 1880**
1488 on the **S.S. Arena** Master **Hellberg**
 Tonnage **729/459** Built at **Sunderland** When built **1873**
 By whom built **Davison** Owners **W. Thorburn**
 Port belonging to **Udddevalla** Destined Voyage **Norland**
 If Surveyed Afloat or in Dry Dock **On Slip**

Last Survey, No. **24196** Port of **Gron** Classified **90A**
 Present Condition of the
 Decks **Good** Treenails **Good**
 Waterways **ditto** Breasthooks and Stemson **Good**
 Comings **do** Transoms, Pointers, and Crutches **do**
 Upper Deck Beams & Fastenings **do** Timbers of the Frame at the Openings **do**
 Lower Deck Beams & Fastenings **do** Ditto ditto at other places **do**
 Planksheers **-** Keelsons **do**
 Sheerstrakes **do** Clamps and Shelves **-**
 Topsides **do** Ceiling **do**
 Wales **do** Rudder **do**
 Plank (Bottom) and Counter **do** Copper or Y.M. **-** When put on **-**
 Caulking of Bottom, Deck, & Waterways **do**
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **do**
 General Observations, Opinion as to Class, &c.

The vessel is now in good and efficient state, fit for the conveyance of dry and perishable goods to and from all parts of the world and in my opinion merits the favorable consideration of the Committee to be continued 90A.

Committee's Minute **Tuesday, October, 5th 1880.**
 Character assigned **90A** **C. R. Moller** Surveyor to Lloyd's Register of British and Foreign Shipping.
B. M. S. 9, 80 Certificate (if required) **18**

No. Survey held at **Date, first Survey** Last Survey **18**
 No. in Reg. Book. on the **Master**
Tonnage Built at **When built**
 By whom built **Owners**
 Port belonging to **Destined Voyage**
 If Surveyed Afloat or in Dry Dock

Last Survey, No. **Port of** Classified **Years assigned.** Character in Register Book.
 Present Condition of the
 Decks **Treenails**
 Waterways **Breasthooks and Stemson**
 Comings **Transoms, Pointers, and Crutches**
 Upper Deck Beams & Fastenings **Timbers of the Frame at the Openings**
 Lower Deck Beams & Fastenings **Ditto ditto at other places**
 Planksheers **Keelsons**
 Sheerstrakes **Clamps and Shelves**
 Topsides **Ceiling**
 Wales **Rudder**
 Plank (Bottom) and Counter **Copper or Y.M.** When put on **Cables**
 Caulking of Bottom, Deck, & Waterways **Hawsers and Warps**
 Engine Room Skylights **Coal Bunkers, Openings, Lids, &c.** Scuppers **Cargo and Main Hatchways** Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute **18**
 Character assigned **Surveyor to Lloyd's Register of British and Foreign Shipping.**
 Certificate (if required) **18**



IRON 494-0497