

# ANNUAL SURVEYS. 27425

No. 29665 Survey held at London Date, first Survey 22<sup>nd</sup> Sept Last Survey 23<sup>rd</sup> Sept 1880  
 No. in on the Iron S. "Deva" Master J. G. Robinson  
 Reg. Book. 440 Tonnage 492 Built at Liverpool When built 1873  
 By whom built Boyd Owners W. Rankin  
 Port belonging to Greenock Destined Voyage Algoa Bay  
 If Surveyed Afloat or in Dry Dock Commercial Dry Dock

Last Survey, No. 44487 Port of Iron Classed 100 A 1  
 Present Condition of the  
 Decks Good Greenails Rivets Good S.S. Dir. No. 1-77 9-79  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes Plating " Clamps and Shelves "  
 Topsides " " Ceiling "  
 Wales " " Rudder "  
 Plank (Bottom) and Counter " " Copper or Y.M. Coating When put on Now  
 Caulking of "  
 Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers " Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c.

Examined in Dry Dock, timbers lifted & cement found good, bottom cleaned & coated; she is eligible, in my opinion to continue as classed

Committee's Minute Tuesday, October, 5th 1880.  
 Character assigned 100 A 1 James Purpin  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) TRW Paid 18

No. 670 Survey held at London Date, first Survey 22 Sept Last Survey 23<sup>rd</sup> Sept 1880  
 No. in on the Iron S. "Grecian" Master Corrance  
 Reg. Book. 1194 Tonnage 1332 Built at Greenock When built 1868  
 By whom built 1273 Scott Owners W. Orr  
 Port belonging to Greenock Destined Voyage Cape Town  
 If Surveyed Afloat or in Dry Dock Regent Dry Dock

Last Survey, No. 24571 Port of Iron Classed A 1 - 9-79  
 Present Condition of the  
 Decks Good Greenails Rivets Good S.S. Dir. No. 2 77  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes Plating " Clamps and Shelves "  
 Topsides " " Ceiling "  
 Wales " " Rudder "  
 Plank (Bottom) and Counter " " Copper or Y.M. Coating When put on Now  
 Caulking of "  
 Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers " Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c.

Examined in Dry Dock, timbers lifted & cement found good, bottom cleaned & coated; she is eligible, in my opinion, to continue as classed

Committee's Minute Tuesday, October, 5th 1880.  
 Character assigned 100 A 1 James Purpin  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) TRW Paid 18