

ANNUAL SURVEYS.

No. 3343 Survey held at Barrow Date, first Survey 7th April Last Survey 20th April 1880.
 No. in on the Ship "England's Glory" Master M. Knight
 Reg. Book. 756 Tonnage 751 Built at Liverpool When built 1869 - 3mo.
 By whom built Pile Owners E. B. R. Moore
 Port belonging to London Destined Voyage Port Augusta, West Australia
 If Surveyed Afloat or in Dry Dock Afloat & in Dry Dock.

Last Survey, No. 21441 Port of Liverpool Iron

Classed - Years assigned - Character in Register Book * A1

Present Condition of the

Decks	<u>Good</u>	Trunnels	<u>Good</u>	Rivets	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>50</u>	Breasthooks and Stemson	<u>50</u>	Transoms, Pointers, and Crutches	<u>50</u>	Pumps	<u>50</u>
Comings	<u>50</u>	Timbers of the Frame at the Openings	<u>50</u>	Ditto ditto at other places	<u>Not seen</u>	Boats	<u>50</u>
Upper Deck Beams & Fastenings	<u>50</u>	Keelsons	<u>(Part seen) Good</u>	Clamps and Shells	<u>Strung</u>	Masts, Yards, &c.	<u>50</u>
Lower Deck Beams & Fastenings	<u>50</u>	Ceiling	<u>(Part seen) 50</u>	Rudder	<u>50</u>	Condition, how ascertained	<u>By examination from deck. Good</u>
Planksheers	<u>50</u>	Copper or Y.M. Cement	<u>When put on 1869.</u>	Caulking of	<u>Good</u>	Sails	<u>Good</u>
Sheerstrakes	<u>50</u>	Bottom, Deck, & Waterways	<u>Good</u>	Standing and Running Rigging	<u>50</u>	Anchors, No. of	<u>3 R. 1 L. 34.</u>
Topsides	<u>50</u>	Engine Room Skylights	<u>-</u>	Coal Bunker, Openings, Lids, &c.	<u>-</u>	Cables	<u>(Not ranged) Good</u>
Wales	<u>50</u>	Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>	Hawsers and Warps	<u>50</u>
Plank (Bottom) and Counter	<u>50</u>	Hatches	<u>50</u>				

General Observations, Opinion as to Class, &c.

Examined in Barrow dry dock - bottom cleaned and coated - rudder bushed.
This vessel appears to be in good condition and is eligible in my opinion, to remain as classed - * A1.

Committee's Minute Friday, September 24th 1880

Character assigned

F. B. W.

William Bath.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) See L.R. 1.0 Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

Present Condition of the

Decks		Trunnels		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shells		Anchors, No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper or Y.M.	<u>When put on</u>	Standing and Running Rigging	
Engine Room Skylights		Caulking of			
Coal Bunkers, Openings, Lids, &c.		Bottom, Deck, & Waterways			
Scuppers					
Cargo and Main Hatchways					
Hatches					

General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18