

# ANNUAL SURVEYS. 27753

No. 27203 Survey held at Liverpool Date, first Survey 26<sup>th</sup> Aug Last Survey 6<sup>th</sup> Sept 18 80  
 No. in on the Ship Montgomeryshire Master Steward  
 Reg. Book. 1401 Tonnage 1452 Built at Liverpool When built 1877 - 6 mo  
1225 By whom built Royden Owners Hughes & Co.  
 Port belonging to Liverpool Destined Voyage Rangoon  
 If Surveyed Afloat or in Dry Dock Princes Bay Dock.

Last Survey, No. 25110 Port of Iron Classed 100 A.1.  
 Years assigned. 11-79 Character in Register Book.

Present Condition of the  
 Decks Good Ironails Rivets Good  
 Waterways --- Breasthooks and Stimson ---  
 Comings --- Transoms, Pointers, and Crutches ---  
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings ---  
 Lower Deck Beams & Fastenings --- Ditto ditto at other places ---  
 Planksheers --- Keelsons ---  
 Sheerstrakes --- Clamps and Shelves ---  
 Topsides --- Ceiling ---  
 Wales --- Rudder ---  
 Plate --- Copper or Y.M. Cent When put on 77  
 Plank (Bottom) and Counter --- Caulking of  
Engine Room Skylights Coat Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom examined cleaned and coated with Patent Composition.

Vessel in good and efficient condition and eligible to remain as classed.

Committee's Minute Liverpool 28<sup>th</sup> Sept 18 80  
 Character assigned 100 A.1.

T. W. Blayell.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) --- Paid --- 18 ---

No. 23448 Survey held at Liverpool Date, first Survey 31<sup>st</sup> Aug Last Survey 31<sup>st</sup> Aug 18 80  
 No. in on the S. "Frankfurt Hall" Master Armstrong  
 Reg. Book. 728 Tonnage 748 Built at Liverpool When built 1869 - 9 mo  
700 By whom built Evans Owners Friend & Co.  
 Port belonging to Liverpool Destined Voyage Valparaiso.  
 If Surveyed Afloat or in Dry Dock Clarence Bay Dock

Last Survey, No. 23448 Port of Iron Classed 100 A.1.  
 Years assigned. 11-79 Character in Register Book.

Present Condition of the  
 Decks Good Ironails Rivets Good  
 Waterways --- Breasthooks and Stimson ---  
 Comings --- Transoms, Pointers, and Crutches ---  
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings ---  
 Lower Deck Beams & Fastenings --- Ditto ditto at other places ---  
 Planksheers --- Keelsons ---  
 Sheerstrakes --- Clamps and Shelves ---  
 Topsides --- Ceiling ---  
 Wales --- Rudder ---  
 Plate --- Copper or Y.M. Cent When put on 69  
 Plank (Bottom) and Counter --- Caulking of  
Engine Room Skylights Coat Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom examined cleaned and coated with Paint & Tallow.

Vessel in good and efficient condition and eligible to remain as classed.

Committee's Minute Liverpool 28<sup>th</sup> Sept 18 80  
 Character assigned 100 A.1.

T. W. Blayell.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) --- Paid --- 18 ---



ANNUAL SURVEYS  
Montgomeryshire  
Frankfort Hall

27203



© 2019

Lloyd's Register  
Foundation