

ANNUAL SURVEYS.

27784

(Received at London Office,

No. 15001 Survey held at South Shields Date, first Survey 26 Aug. Last Survey 26 Aug. 1880
 No. in on the Scw. Sr. "John Johnasson" Master Gordon
 Reg. Book. 4849 Tonnage 55 Built at Newcastle When built 1870 — 5 mo
 By whom built Mitchell Owners Gordon & Stamp
 Port belonging to London Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock H. S. Edwards & Sons Dock

Last Survey, No. 2556 Port of Iron

Classed

Years assigned.

Character in Register Book.

A 1

1-80

Present Condition of the

Decks Gova
 Waterways "
 Comings "
 Upper Deck Beams & Fastenings "
 Lower Deck Beams & Fastenings "
 Planksheers "
 Sheerstrakes "
 Topsides "
 Wales "
 Plank (Bottom) and Counter "

Treenails Rivets
 Breasthooks and Stemson Not Seen
 Transoms, Pointers, and Crutches "
 Timbers of the Frame at the Openings Gova
 Ditto ditto at other places "
 Keelsons "
 Clamps and Shelves "
 Ceiling "
 Rudder "
 Copper or P.M. Cement When put on 1870
 Caulking of Bottom, Deck, & Waterways Gova

Windlass and Capstan

Pumps MetalBoats 3 H.Masts, Yards, &c. in when practicable
Condition, how ascertained

Sails

Anchors, No. of 3 B. 15. 2 H.Cables Not Seen

Hawsers and Warps

Standing and Running Rigging

Good

and

Sufficient

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Sighted bottom; The outer surface of the shell plating coated with 2 coats of Anglo-German composition up to the ballast-marks and 1 coat of paint above up to about 11 ft. The vessel appears now in good & efficient state of repair & eligible in my opinion to remain as classed

Committee's Minute

Tuesday, September, 14th 1880.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) — Paid — 18 —

No. 305 Survey held at South Shields Date, first Survey 31 Aug. Last Survey 31 Aug. 1880
 No. in on the Scw. Sr. "Viola" Master Stephens
 Reg. Book. 2783 Tonnage 196 Built at Newcastle When built 1879 — 10 mo
 By whom built Gyne Co. Owners J. Robinson & Co.
 Port belonging to North Shields Destined Voyage America
 If Surveyed Afloat or in Dry Dock H. S. Edwards & Sons Dock

Last Survey, No. 2576 Port of Iron

Classed

Years assigned.

Character in Register Book.

100 A 1

11-49

Present Condition of the

Decks Gova
 Waterways "
 Comings "
 Upper Deck Beams & Fastenings "
 Lower Deck Beams & Fastenings "
 Planksheers "
 Sheerstrakes "
 Topsides "
 Wales "
 Plank (Bottom) and Counter "

Treenails Rivets
 Breasthooks and Stemson Not Seen
 Transoms, Pointers, and Crutches "
 Timbers of the Frame at the Openings Gova
 Ditto ditto at other places "
 Keelsons "
 Clamps and Shelves "
 Ceiling "
 Rudder "
 Copper or P.M. Cement When put on 79
 Caulking of Bottom, Deck, & Waterways Gova

Windlass and Capstan

Pumps MetalBoats 4 H.Masts, Yards, &c. in when practicable
Condition, how ascertained

Sails

Anchors, No. of 3 B. 15. 2 H.Cables Not Seen

Hawsers and Warps

Standing and Running Rigging

Good

and

Sufficient

Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Sighted bottom. The outer surface of shell plating scraped down and coated with 2 coats of paint and 1 coat of zinc primer composition and 2 coats of paint above up to about 15 ft. She is now in good & efficient condition and eligible in my opinion to remain as classed

Committee's Minute

Tuesday, September, 14th 1880.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) — Paid — 18 —