

ANNUAL SURVEYS.

27798
25th Aug 80

No. 29529 Survey held at London Date, first Survey 11th Aug Last Survey 13th Aug 1880
 No. in on the Reg. Book. 53 Tonnage 528 Built at Newcastle Master A. W. Wood
 By whom built Palmer's Owners Membe & Howard
 Port belonging to London Destined Voyage Newcastle
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 44552 Port of Irish Classed 90 A 1 Years assigned. 9-79 Character in Register Book.

Present Condition of the Decks	<u>Good</u>	<u>Treenails</u>	<u>Rivets</u>	<u>Good</u>	
Waterways	"	Breasthooks and Stemson		"	Windlass and Capstan <u>Good</u>
Comings	"	Transoms, Pointers, and Crutches		"	Pumps
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Boats <u>3 in No 2</u>
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Masts, Yards, &c.
Planksheers	"	Keelsons		<u>Not seen</u>	Condition, how ascertained <u>from deck</u>
Sheerstrakes	"	Clamps and Shelves		<u>Good</u>	Sails <u>Good</u>
Topsides	"	Ceiling		"	Anchors, No. of <u>3 B. 1 S. 2 K</u>
Wales	"	Rudder		"	Cables <u>Complete &</u>
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coating</u> When put on <u>Now</u>		"	Hawsers and Warps
Engine Room Skylights <u>Good</u> Coal Bunker, Openings, Lids, &c. <u>Good</u> Scuppers			Caulking of Bottom, Deck, & Waterways <u>Good</u>		Standing and Running Rigging
General Observations, Opinion as to Class, &c.					Cargo and Main Hatchways <u>Good</u> Hatches

Examined outside and inside as far as practicable and found everything in good condition, & she is, in my opinion, eligible to remain as classed.

Committee's Minute Friday, August 27th 1880
 Character assigned 90 A 1
 Surveyor to Lloyd's Register of British and Foreign Shipping. James Surpin
 Certificate (if required) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the Reg. Book. _____ Tonnage _____ Built at _____ Master _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book.

Present Condition of the Decks	<u>Good</u>	<u>Treenails</u>	<u>Rivets</u>	<u>Good</u>	
Waterways	"	Breasthooks and Stemson		"	Windlass and Capstan
Comings	"	Transoms, Pointers, and Crutches		"	Pumps
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Boats
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Masts, Yards, &c.
Planksheers	"	Keelsons		"	Condition, how ascertained
Sheerstrakes	"	Clamps and Shelves		"	Sails
Topsides	"	Ceiling		"	Anchors, No. of
Wales	"	Rudder		"	Cables
Plank (Bottom) and Counter	"	Copper or Y.M. _____ When put on _____		"	Hawsers and Warps
Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____			Caulking of Bottom, Deck, & Waterways _____		Standing and Running Rigging _____
General Observations, Opinion as to Class, &c.					Cargo and Main Hatchways _____ Hatches _____

Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required) Paid 18

