

ANNUAL SURVEYS.

(Received at London Office, 31/8/86)

No. 3955 Survey held at Bristol Date, first Survey 24 July 1885 Last Survey 25 August 1885
 No. in on the Sew Mary Louisa Master Mace
 Reg. Book. 7/2 Tonnage 1287 Built at Newcastle When built 1876 5mo
 By whom built Mitchell Owners Elliott, Lourey & Dunford
 Port belonging to Newcastle Destined Voyage N. America
 If Surveyed Afloat or in Dry Dock Great Western Dry Dock

Last Survey, No. 21215 Port of Iron Classed 100A 1 Years assigned. 7-79 Character in Register Book.

Present Condition of the Decks <u>Good</u>	Treenails <u>Rivets</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	<u>Ditto</u> ditto at other places <u>"</u>	Condition, how ascertained <u>From deck</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Good</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors, No. of <u>3B 1S 2K</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>part seen</u> <u>Good</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Cluent</u> When put on <u>78</u>	Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Scuppers <u>"</u>	Hatches <u>"</u>

General Observations, Opinion as to Class, &c. Vessel placed in dry dock - her bottom cleaned and painted - Some rivets in rudder renewed.
She is now in a good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute Friday, September 3rd 1886 Surveyor J. Pearce
 Character assigned 100A 1 Certificate (if required) J.P.W. Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Cargo and Main Hatchways _____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Hatches _____

Committee's Minute _____ 18____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required) _____ Paid _____ 18____

