

ANNUAL SURVEYS. 27859

Survey held at London Date, first Survey 24th Sept^r Last Survey 24th Sept^r 1880
 No. in on the Iron Scw. Sr. "Ossian." Master Jefferson
 Reg. Book. 309 Tonnage 1211 Built at Newcastle When built 1876 - 9mo.
 By whom built Swan. Owners Glover Bros.
 Port belonging to London. Destined Voyage Bombay via Glasgow.
 If Surveyed Afloat or in Dry Dock In Millwall Dry Docks.

Last Survey, No. 27418 Port of Iron Classed 100 A-1.
 Years assigned. 7.80 Character in Register Book.
 Present Condition of the
 Decks good Treennails rivets good
 Waterways g^o Breasthooks and Stemson g^o
 Comings g^o Transoms, ~~Pointers~~, and Crutches g^o
 Upper Deck Beams & Fastenings g^o ~~Timbers~~ of the Frame at the Openings g^o
 Lower Deck Beams & Fastenings g^o Ditto ditto at other places g^o
 Planksheers g^o Keelsons g^o
 Sheerstrakes g^o Clamps and Shelves g^o
 Topsides g^o Ceiling g^o
 Wales g^o Rudder g^o
 Plank (Bottom) and Counter g^o Copper or Y.M. When put on
 Caulking of good
 Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps g^o
 Boats g^o
 Masts, Yards, &c. g^o
 Condition, how ascertained from the deck
 Sails good
 Anchors, No. of 3.B. 1.S. 2.K
 Cables complete
 Hawsers and Warps sufficient
 Standing and Running Rigging g^o
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

The bottom has been examined, cleaned and coated.
The attention of the Owners' Representative has been called to the fact that
S.S. No 1 is nearly due - which survey it appears will be carried out on the
vessel's return.
This vessel appears to be eligible to remain as classed.
 Committee's Minute Friday, October 1st 1880
 Character assigned 100 A-1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 Last Survey, No. Port of Classed
 Years assigned. Character in Register Book.
 Present Condition of the
 Waterways Treennails
 Comings Breasthooks and Stemson
 Upper Deck Beams & Fastenings Transoms, Pointers, and Crutches
 Lower Deck Beams & Fastenings Timbers of the Frame at the Openings
 Planksheers Ditto ditto at other places
 Sheerstrakes Keelsons
 Topsides Clamps and Shelves
 Wales Ceiling
 Plank (Bottom) and Counter Rudder
 Copper or Y.M. When put on
 Caulking of
 Bottom, Deck, & Waterways
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors, No. of
 Cables
 Hawsers and Warps
 Standing and Running Rigging
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

