

# ANNUAL SURVEYS.

27883

No. 39. Survey held at Antwerp Date 8-10 September 1880.  
 on the S.S. "Rio-Lima" Master A. Villan  
 Tonnage 185 Built at Newcastle When built 1872-8 mo  
 By whom built Scotland Owners Compañia de Navegacion  
 Port belonging to Puerto Destined Voyage Puerto-Rico  
 If Surveyed Afloat or in Dry Dock in dry dock

Last Survey, No. 24132 Port of Iron

Classed 90 A. 1.  
 3-78  
 S. S. No. 1-78

The present Condition of the

Decks good  
 Waterways "  
 Comings "  
 Upper Deck Beams & Fastenings "  
 Lower Deck Beams & Fastenings "  
 Planksheers "  
 Sheerstrakes "  
 Topsides "  
 Wales "  
 Plank (Bottom) and Counter "

Treenails Rivets good  
 Breasthooks and Stenson "  
 Transoms, Pointers, and Crutches "  
 Timbers of the Frame at the Openings "  
 Ditto ditto at other places "  
 Keelsons "  
 Clamps and Shelves "  
 Ceiling "  
 Rudder "  
 Copper Good For When put on new

Windlass and Capstan good  
 Pumps "  
 Boats "  
 Masts, Yards, &c. "  
 Sails "  
 Anchors No. of 5 "  
 Cables "  
 Hawsers and Warps "  
 Standing & Running Rigging "

General Observations and Opinion,

Shard in dry dock and surveyed by me at. Agents request all outside & inside, as far as practicable, and found all in good condition, the vessel fit to carry dry & perishable goods and worthy continuation of present class.

Committee's Minute Tuesday, September, 14th 1880.

Character assigned 90 A. 1.

Certificate (if required) yes

No. Survey held at Date 18  
 on the Master  
 Tonnage Built at When built  
 By whom built Owners  
 Port belonging to Destined Voyage  
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

The present Condition of the

Decks  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers  
 Sheerstrakes  
 Topsides  
 Wales  
 Plank (Bottom) and Counter

Treenails  
 Breasthooks and Stenson  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the Openings  
 Ditto ditto at other places  
 Keelsons  
 Clamps and Shelves  
 Ceiling  
 Rudder  
 Copper When put on

Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Sails  
 Anchors No. of  
 Cables  
 Hawsers and Warps  
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute 18

Character assigned



© 2019

Lloyd's Register  
 Foundation

IRON495-0228