

# ANNUAL SURVEYS.

27925  
(Recd 11.9.80)

No. 29600 Survey held at London Date, first Survey Sept 4<sup>th</sup> Last Survey Sept 4<sup>th</sup> 18 80  
 No. in on the SS Viceroy Master Murdoch  
 Reg. Book. 56 Tonnage 1864 Built at London When built 1871  
 By whom built R. & H. Green Owners R. & H. Green  
 Port belonging to London Destined Voyage Balemma  
 If Surveyed Afloat or in Dry Dock Green Dry Dock

Last Survey, No. 25428 Port of Iron Classed SS Lon No 280  
 Years assigned. 100 A. 1-80 Character in Register Book.

Present Condition of the Decks	<u>good</u>	Treenails <u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u>good</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Condition, how ascertained	<u>Iron &amp;</u>
Planksheers	"	Keelsons	"	Sails	<u>good</u>
Sheerstrakes	"	Clamps and Shelves	"	Anchors, No. of <u>3 Nos. No. 1 &amp; 2</u>	<u>good</u>
Topsides	"	Ceiling	"	Cables <u>Caston &amp;c</u>	<u>good</u>
Wales	"	Rudder	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>bottom</u> When put on <u>now</u>	"	Standing and Running Rigging	"
Engine Room Skylights	<u>good</u>	Caulking of Bottom, Deck, & Waterways	<u>good</u>	Cargo and Main Hatchways	<u>good</u>
General Observations, Opinion as to Class, &c.	<u>Coal Bunker, Openings, Lids, &amp;c. good Scuppers good Hatches 3</u> <u>Bottom &amp;c coated.</u>				

*She is now in good condition and eligible to remain as classed.*

Committee's Minute Tuesday, September, 14th 1880.

Character assigned 100 A  
TRW

S Murdoch  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)          Paid          18         

No.          Survey held at          Date, first Survey          Last Survey          18           
 No. in on the          Master           
 Reg. Book.          Tonnage          Built at          When built           
 By whom built          Owners           
 Port belonging to          Destined Voyage           
 If Surveyed Afloat or in Dry Dock         

Last Survey, No.          Port of          Classed           
 Years assigned.          Character in Register Book.

Present Condition of the Decks	<u>        </u>	Treenails	<u>        </u>	Windlass and Capstan	<u>        </u>
Waterways	<u>        </u>	Breasthooks and Stemson	<u>        </u>	Pumps	<u>        </u>
Comings	<u>        </u>	Transoms, Pointers, and Crutches	<u>        </u>	Boats	<u>        </u>
Upper Deck Beams & Fastenings	<u>        </u>	Timbers of the Frame at the Openings	<u>        </u>	Masts, Yards, &c.	<u>        </u>
Lower Deck Beams & Fastenings	<u>        </u>	Ditto ditto at other places	<u>        </u>	Condition, how ascertained	<u>        </u>
Planksheers	<u>        </u>	Keelsons	<u>        </u>	Sails	<u>        </u>
Sheerstrakes	<u>        </u>	Clamps and Shelves	<u>        </u>	Anchors, No. of <u>        </u>	<u>        </u>
Topsides	<u>        </u>	Ceiling	<u>        </u>	Cables	<u>        </u>
Wales	<u>        </u>	Rudder	<u>        </u>	Hawsers and Warps	<u>        </u>
Plank (Bottom) and Counter	<u>        </u>	Copper or Y.M. <u>        </u> When put on <u>        </u>	<u>        </u>	Standing and Running Rigging	<u>        </u>
Engine Room Skylights	<u>        </u>	Caulking of Bottom, Deck, & Waterways	<u>        </u>	Cargo and Main Hatchways	<u>        </u>
General Observations, Opinion as to Class, &c.	<u>Coal Bunkers, Openings, Lids, &amp;c. Scuppers Hatches</u>				

Committee's Minute          18         

Character assigned         

          
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)          Paid          18         

