

ANNUAL SURVEYS.

No. 39594 Survey held at London Date, first Survey 19 July/80 Last Survey 7 Sept 80 1880
 No. in on the Iron Bk "Star of Albion" Master J. Hughes.
 Reg. Book. 1028. Tonnage 999 Built at Belfast When built 1864-7mo.
 By whom built Harland Owners J. Corry & Co.
 Port belonging to Belfast Destined Voyage Calcutta.
 If Surveyed Afloat or in Dry Dock In the Canal Dry Dock.

Last Survey, No. 22664 Port of Iron Classed L.L. Lon. N^o 3-77. Years assigned. 1.79. Character in Register Book. *A. 1

Present Condition of the	<u>good</u>	<u>rivets</u>	<u>good.</u>	
Decks	<u>J^o</u>	Breasthooks and Stemson	<u>J^o</u>	Windlass and Capstan <u>good</u>
Waterways	<u>J^o</u>	Transoms, <u>Pointers</u> , and Crutches	<u>J^o</u>	Pumps <u>J^o</u>
Comings	<u>J^o</u>	Timbers of the Frame at the Openings	<u>J^o</u>	Boats <u>4-J^o</u>
Upper Deck Beams & Fastenings	<u>J^o</u>	<u>Ditto</u> ditto at other places	<u>J^o</u>	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings	<u>J^o</u>	Keelsons	<u>J^o</u>	Condition, how ascertained <u>from the deck</u>
Planksheers	<u>J^o</u>	Clamps and Shelves	<u>J^o</u>	Sails <u>good</u>
Sheerstrakes	<u>J^o</u>	Ceiling	<u>J^o</u>	Anchors, No. of <u>3 B. 1 S. 2 K.</u>
Topsides	<u>J^o</u>	Rudder	<u>J^o</u>	Cables <u>complete</u>
Wales	<u>J^o</u>	Copper or Y.M.	<u>When put on</u>	Hawsers and Warps <u>sufficient</u>
Plating	<u>J^o</u>	Caulking of	<u>good</u>	Standing and Running Rigging <u>J^o</u>
Bottom (Bottom) and Counter	<u>J^o</u>	Bottom, Deck, & Waterways	<u>good</u>	Cargo and Main Hatchways <u>good</u>
Engine Room Skylights	<u>Coal Bunkers, Openings, Lids, &c.</u>	Scuppers	<u>good</u>	Hatches <u>good</u>

General Observations, Opinion as to Class, &c.
The bottom has been examined, cleaned & coated; the rudder pintles rebushed.
The spanker boom has been renewed of pitch pine.
Vessel surveyed with a quantity of ballast & part outboard cargo in the hold.
She appears to be eligible to remain as classed.

Committee's Minute Tuesday, September, 14th 1880.
 Character assigned J. H. Truscott.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed Years assigned. Character in Register Book.

Present Condition of the			
Decks	Treenails	Windlass and Capstan	
Waterways	Breasthooks and Stemson	Pumps	
Comings	Transoms, Pointers, and Crutches	Boats	
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained	
Planksheers	Keelsons	Sails	
Sheerstrakes	Clamps and Shelves	Anchors, No. of	
Topsides	Ceiling	Cables	
Wales	Rudder	Hawsers and Warps	
Plating	Copper or Y.M.	Standing and Running Rigging	
Bottom (Bottom) and Counter	Caulking of	Cargo and Main Hatchways	
Engine Room Skylights	Bottom, Deck, & Waterways	Hatches	
Coal Bunkers, Openings, Lids, &c.	Scuppers		

General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

