

# REPORT of SURVEY for REPAIRS, &c.

No. *4926* *Newport (Man)* Date, first Survey *25<sup>th</sup> August* Last Survey *28<sup>th</sup> August* 1880.  
 Reg. Book. *595* on the *Synedale* Master *Evans*  
 TONNAGE under Tonnage Deck *476* Built at *Sunderland* When built *1868*  
 Ditto of Spar Deck, or Acreing Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage *508*  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam  
 Engine Room  
 Reg. Tons as S<sup>r</sup>mer, cut on Bm. *325*  
 Owners *Barrow & Continental S. Ship Co.* Port belonging to *Barrow*  
 Residence  
 By whom built *Lainy* Destined Voyage *Bilbao*  
 X Surveyed Afloat or in Dry Dock (State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.  
 Last Survey, No. *26054* Port *Iron*  
 REPAIRS, OR EXAMINATION AS PER RULE  
 Cause of Repairs to be clearly stated.

*Survey on account of damage sustained in consequence of a fender cutting a plate whilst lying at Portgalette on the 19<sup>th</sup> August 1880.*

*Vessel seen with a full cargo on board. One plate in fore-bow in stroke below sheerstrake renewed, properly riveted and caulked.*

## Present Condition of the

### Decks

### Waterways

### Comings

### Upper Deck Beams & Fastenings

### Lower Deck Beams & Fastenings

### Planksheers

### Sheerstrakes

### Topsides

### Vales

### Plank (Bottom) and Counter

### Engine Room Skylights

### General Observations, Opinion as to Class, &c.

### Treenails

### Breasthooks and Stemson

### Transoms, Pointers, and Crutches

### Timbers of the Frame at the openings

### Ditto Ditto at other places

### Keelsons

### Clamps and Shelves

### Ceiling

### Rudder

### Copper (or Y.M.)

### When put on

### Caulking of

### Bottom, Deck, & Waterways

### Windlass and Capstan

### Pumps

### Boats

### Masts, Yards, &c.

### Condition, how ascertained

### Sails

### Anchors No. of

### Cables

### Hawsers and Warps

### Standing & Running Rigging

### Cargo and Main Hatchways

### Hatches

The Amount of Entry Fee ... £ : : received by me, *1499*  
 Special ... £ 2 : 2 : *79* 1880  
 Certificate (if required) to be sent as per margin... £ : :

Travelling Expenses, if any, £ / . s . o .

Committee's Minute

Tuesday, September, 7th 1880

Character assigned

*B* as now

*H. Keydell*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON495-0327



*Lynedale*



© 2019

Lloyd's Register  
Foundation