

ANNUAL SURVEYS.

27944

No. 2921 Survey held at London Date, first Survey 6th Oct Last Survey 7th Oct 1880
 No. in on the Gen Secor S^r Fairfax Master Butler
 Reg. Book. 14 Tonnage 409 Built at Glasgow When built 1865
 By whom built Gen. & Glas. Co. Owners General S. C.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Lincoln Dry Dock

Last Survey, No. 7504 Port of Iron S.S. do. 3-12 Classed 90 A 1
 Present Condition of the Decks Good Treenails Rivets Good S.S. No. 1
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes Plating Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coating When put on Iron
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers " Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. _____

She is in good condition and eligible, in my opinion to continue, as classed

Committee's Minute Tuesday, October, 19th 1880.
 Character assigned 90 A 1
 Surveyor to Lloyd's Register of British and Foreign Shipping. James Surpin
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required) _____ Paid _____ 18 _____



H530-561201