

# ANNUAL SURVEYS.

27996

No. 39704 Survey held at London. Date, first Survey 2<sup>nd</sup> Oct<sup>r</sup> Last Survey 2<sup>nd</sup> Oct<sup>r</sup> 1880.  
 No. in on the Iron S.W. Sr. "Stork." Master B. P. Wilkins.  
 Reg. Book. 543 Tonnage 1124 Built at Dundee When built 1864-7 mo.  
 By whom built Gourlay Owners General Steam Navigation Co.  
 Port belonging to London Destined Voyage Hamburg.  
 If Surveyed Afloat or in Dry Dock On the Gridiron of the Gen. Stm. Nav. Co. Deptford.

Last Survey, No. 22240 Port of Iron Classed L.S. Lon. No 3-78 Years assigned. A.1. Character in Register Book. 10.78  
 Present Condition of the  
 Decks good Treanails rivets good  
 Waterways 5<sup>o</sup> Breasthooks and Stenson 5<sup>o</sup>  
 Comings 5<sup>o</sup> Transoms, ~~Pointers~~, and Crutches 5<sup>o</sup>  
 Upper Deck Beams & Fastenings 5<sup>o</sup> ~~Timbers~~ of the Frame at the Openings 5<sup>o</sup>  
 Lower Deck Beams & Fastenings 5<sup>o</sup> Ditto ditto at other places 5<sup>o</sup>  
 Planksheers 5<sup>o</sup> Keelsons 5<sup>o</sup>  
 Sheerstrakes 5<sup>o</sup> Clamps and Shelves 5<sup>o</sup>  
 Topsides 5<sup>o</sup> Ceiling 5<sup>o</sup>  
 Wales 5<sup>o</sup> Rudder 5<sup>o</sup>  
 Plank (Bottom) and Counter 5<sup>o</sup> Copper or Y.M. When put on  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good.  
 General Observations, Opinion as to Class, &c.

The bottom has been examined, cleaned and coated.  
Four upper deck planks on the port side renewed of pitch pine, and the deck recaulked.  
This vessel appears to be eligible to remain as classed.  
No ballast tanks fitted in this vessel.

Committee's Minute Friday, October 15<sup>th</sup> 1880  
 Character assigned J. H. Truscott.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No.            Survey held at            Date, first Survey            Last Survey            18            
 No. in on the            Master             
 Reg. Book.            Tonnage            Built at            When built             
 By whom built            Owners             
 Port belonging to            Destined Voyage             
 If Surveyed Afloat or in Dry Dock           

Last Survey, No.            Port of            Classed            Years assigned.            Character in Register Book.             
 Present Condition of the  
 Decks            Treanails             
 Waterways            Breasthooks and Stenson             
 Comings            Transoms, Pointers, and Crutches             
 Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings             
 Lower Deck Beams & Fastenings            Ditto ditto at other places             
 Planksheers            Keelsons             
 Sheerstrakes            Clamps and Shelves             
 Topsides            Ceiling             
 Wales            Rudder             
 Plank (Bottom) and Counter            Copper or Y.M. When put on  
 Caulking of Bottom, Deck, & Waterways             
 Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers            Cargo and Main Hatchways            Hatches             
 General Observations, Opinion as to Class, &c.           

Committee's Minute            18            
 Character assigned             
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)            Paid            18