

# ANNUAL SURVEYS.

28062

(Received at London Office,

7. 10. 80

No. 39680

Survey held at

London

Date, first Survey

Sept 18<sup>th</sup>

Last Survey

Sept 25<sup>th</sup>

18 80

No. in on the

Reg. Book.

504

Tonnage

14 11

Built at

Glasgow

When built

1871. 10.

By whom built

San & Glas Co

Owners

M<sup>r</sup> Gregor How & Co

Port belonging to

Glasgow

Destined Voyage

Cardiff

If Surveyed Afloat or in Dry Dock

Greens by St

Last Survey, No.

25494

Port of

Iron

Classed

Years assigned.

100A 1.80

Character in Register Book.

S.S. Gms M2-75

Present Condition of the

Decks *Good* Treenails *Drifts* *Good*

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

*Good*

Scuppers

*Good*

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

*Bottom &c coated.*

*She is now in good condition and eligible to remain as classed.*

*Kedge anchor now supplied 5-1-3 tested to 7-14-0-7. Notherton Pump House dated Sept 17<sup>th</sup> 1880. Certificate produced.*

Committee's Minute

Tuesday, October, 12<sup>th</sup> 18 80.

Character assigned

100A

*Senhouse Martin*

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No.

Survey held at

Date, first Survey

Last Survey

18

No. in on the

Reg. Book.

Tonnage

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks Treenails

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Committee's Minute

18


Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18



© 2019

Lloyd's Register

Foundation