

ANNUAL SURVEYS.

28074
Rev 25/10/80

No. 3316 Survey held at Aberdeen Date, first Survey Oct 15 Last Survey Oct 15 1880
 No. in on the James Hall Jun Sen Sr Master Ugubant
 Reg. Book. 42 Tonnage 221 Built at Aberdeen When built 1840 4 months
 By whom built Hall, Russell Owners Aberdeen Castle, Hull & Co
 Port belonging to Aberdeen Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Thos A Hall, & Co Patent slip

Last Survey, No. 24960 Port of Iron Classed Good
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. - When put on -
 Caulking of Bottom, Deck, & Waterways Good where tested
 Windlass and Capstan Good
 Pumps of Iron, efficient
 Boats 3rd good
 Masts, Yards, &c. "
 Condition, how ascertained from examination and enquiry
 Sails Good
 Anchors, No. of 3 Bows 1 stream 1 Keel
 Cables Good
 Hawasers and Warps and sufficient
 Standing and Running Rigging "
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. This vessel appears on examination to be in good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute Tuesday, October, 26th 1880.
 Character assigned Good
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Special S. 1.0 Paid Oct 22 1880

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Windlass and Capstan _____
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Condition, how ascertained _____
 Sails _____
 Anchors, No. of _____
 Cables _____
 Hawasers and Warps _____
 Standing and Running Rigging _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

