

ANNUAL SURVEYS.

38677 Survey held at London Date, first Survey Apr 26 Last Survey Dec 25 1880
on the SS Merkara Master J Ballantine
Tonnage 2571 Built at Gumbarton When built 1875-7
By whom built _____ Owners J Macnair & O Henry
Port belonging to Seny Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock
Last Survey, No. 2552 Port of Iron Classed 100 A. 1. 80
Present Condition of the _____
Decks Good Treenails Rivets Good SS Seny No 75
Waterways _____ Breasthooks and Stemson _____
Comings _____ Transoms, Pointers, and Crutches _____
Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
Planksheers _____ Keelsons _____
Sheerstrakes _____ Clamps and Shelves _____
Topsides _____ Ceiling _____
Wales _____ Rudder _____
Plank (Bottom) and Counter _____ Copper or Y.M. Covered When put on Nov
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches _____
General Observations, Opinion as to Class, &c. Bottom is coated.
She is now in good condition and eligible to remain as classed.

Committee's Minute Tuesday, October, 12th 1880.
Character assigned 100 A. 1
Senhouse Martin
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) 57 Paid 13 Oct 1880

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
No. in _____ on the _____ Master _____
Reg. Book. _____ Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____
Last Survey, No. _____ Port of _____ Classed _____
Present Condition of the _____
Decks _____ Treenails _____
Waterways _____ Breasthooks and Stemson _____
Comings _____ Transoms, Pointers, and Crutches _____
Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
Planksheers _____ Keelsons _____
Sheerstrakes _____ Clamps and Shelves _____
Topsides _____ Ceiling _____
Wales _____ Rudder _____
Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
General Observations, Opinion as to Class, &c. _____

Committee's Minute 18
Character assigned _____
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) _____ Paid _____ 18____