

ANNUAL SURVEYS.

28135

(Received at London Office,

(Rec'd 16th 10. 1880)

1880

39719 Survey held at London Date, first Survey Oct 11 Last Survey Oct 14
in on the S.S. Jaymouth Castle Master J. Gulton
Book. 1172 Tonnage 1827 Built at Glasgow When built 1877. 3
By whom built Barelay Owners J. Currie & Co
Port belonging to London Destined Voyage Cape
If Surveyed Afloat or in Dry Dock James Smiths by St

Last Survey, No. 27543 Port of Iron Classed 100 A & 80
Present Condition of the
Decks Good Treenails Over Good
Waterways Good Breasthooks and Stemson Good
Rimings Good Transoms, Pointers, and Crutches Good
Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
Planksheers Good Keelsons Good
Sheerstrakes Good Clamps and Shelves Good
Upsides Good Ceiling Good
Vales Good Rudder Good
Plank (Bottom) and Counter Good Copper or Y.M. Covered When put on Over
Engine Room Skylights Good Caulking of Bottom, Deck, & Waterways Good
Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Bottom is covered

She is now in good condition and eligible to remain as classed

Committee's Minute Tuesday, October, 19th 1880.
Character assigned 100 A & 80 DSW

Senhouse Martindale
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) 18

No. 39719 Survey held at London Date, first Survey Oct 11 Last Survey Oct 14
in on the S.S. Jaymouth Castle Master J. Gulton
Book. 1172 Tonnage 1827 Built at Glasgow When built 1877. 3
By whom built Barelay Owners J. Currie & Co
Port belonging to London Destined Voyage Cape
If Surveyed Afloat or in Dry Dock James Smiths by St

Last Survey, No. 27543 Port of Iron Classed 100 A & 80
Present Condition of the
Decks Good Treenails Over Good
Waterways Good Breasthooks and Stemson Good
Rimings Good Transoms, Pointers, and Crutches Good
Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
Planksheers Good Keelsons Good
Sheerstrakes Good Clamps and Shelves Good
Upsides Good Ceiling Good
Vales Good Rudder Good
Plank (Bottom) and Counter Good Copper or Y.M. Covered When put on Over
Engine Room Skylights Good Caulking of Bottom, Deck, & Waterways Good
Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Bottom is covered

Committee's Minute 18
Character assigned 100 A & 80

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) 18