

ANNUAL SURVEYS.

39739 28143

No. Survey held at London Date, first Survey Oct 12th Last Survey Oct 14th 1880
 No. in on the SS Sorunda Master Jempleton
 Reg. Book. 1843 Tonnage 2977 Built at Gumbarton When built 1875-10
95 By whom built Senny Owners S Macneil & P Senny
 Port belonging to Glasgow Destined Voyage India
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St

Last Survey, No. 26084 Port of Iron Classed 100 A. 3. 80,
SS Lon No 178 (79)
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " ~~Copper or Y.M.~~ Canted When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom & counter
She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, October 22nd 1880
 Character assigned 100 A. 3. 80 STBW
Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned

 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18



© 2019

Lloyd's Register Foundation