

No. 39456 Survey held at London Date, first Survey 18th Oct Last Survey 21 Oct 1880
 No. in on the Iron Bk "Earl Granville" Master Lampbell
 reg. Book. 34 Tonnage 56.1009.90 Built at Port Glasgow When built 1877-3 mo
 By whom built Duncan Owners A McAlister
 Port belonging to Glasgow Destined Voyage Rockhampton
 If Surveyed Afloat or in Dry Dock Ratcliffe Cross dry Dk

Last Survey, No. 45148 Port of Iron Classed 100 A 1

| | | | |
|--|-------------|-------------|-------------|
| Present Condition of the | <u>Good</u> | <u>Good</u> | <u>Good</u> |
| Decks | <u>Good</u> | <u>Good</u> | <u>Good</u> |
| Waterways | <u>Good</u> | <u>Good</u> | <u>Good</u> |
| Comings | <u>Good</u> | <u>Good</u> | <u>Good</u> |
| Upper Deck Beams & Fastenings | <u>Good</u> | <u>Good</u> | <u>Good</u> |
| Lower Deck Beams & Fastenings | <u>Good</u> | <u>Good</u> | <u>Good</u> |
| Planksheers | <u>Good</u> | <u>Good</u> | <u>Good</u> |
| Sheerstrakes | <u>Good</u> | <u>Good</u> | <u>Good</u> |
| Top-sides | <u>Good</u> | <u>Good</u> | <u>Good</u> |
| Vales | <u>Good</u> | <u>Good</u> | <u>Good</u> |
| Blank (Bottom) and Counter | <u>Good</u> | <u>Good</u> | <u>Good</u> |
| Engine Room Skylights | <u>Good</u> | <u>Good</u> | <u>Good</u> |
| General Observations, Opinion as to Class, &c. | <u>Good</u> | <u>Good</u> | <u>Good</u> |

When put on 1877

Bottom painted also 'tween decks. She is now in good condition and in my opinion eligible to continue as classed

Committee's Minute Tuesday, October, 26th 1880

Character assigned 100 A 1

JBW

© 2019
Willmott & Dacey
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18