

ANNUAL SURVEYS. 28158

(Received at London Office, (Rec'd 22nd 10.80.)

No. _____ Survey held at London Date, first Survey 7th Oct Last Survey 11th Oct 1880
No. in on the Pen New St. Penamain Master R. Bisset
Reg. Book. 297 Tonnage 247 Built at Aberdeen When built 1870 5th mo.
By whom built Wall & Co Owners J. & A. Davidson
Port belonging to Aberdeen Destined Voyage Not known
If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 2306 Port of Iron Classed 100 A 1
Present Condition of the
Treenails Good Rivets Good
Breasthooks and Stemson Good
Transoms, Pointers, and Crutches Good
Timbers of the Frame at the Openings Good
Ditto ditto at other places Good
Keelsons Good
Clamps and Shelves Good
Ceiling Good
Rudder Good
Copper or Y.M. Coating When put on Now
Caulking of Good
Bottom, Deck, & Waterways Good
Windlass and Capstan Good
Pumps 3 in No 2
Boats 2 in No 2
Masts, Yards, &c. Good
Condition, how ascertained from deck
Sails Complete & good
Anchors, No. of 3 B. 1 S. 1 K.
Cables Complete & good
Hawsers and Warps Good
Standing and Running Rigging Good
Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. She is in good condition, and eligible, in my opinion, to continue as classed

Committee's Minute Friday, October 22nd 1880
Character assigned 100 A 1
James Surpin
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) 5/- Paid 2nd Oct 1880

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
No. in on the _____ Master _____
Reg. Book. _____ Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
Present Condition of the
Decks
Waterways
Tomings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Gangsheers
Deerstrakes
Sides
Plates
Hulk (Bottom) and Counter
Cabin Room Skylights
Coal Bunkers, Openings, Lids, &c.
Scuppers
Cargo and Main Hatchways
Hatches
Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places
Keelsons
Clamps and Shelves
Ceiling
Rudder
Copper or Y.M. When put on
Caulking of
Bottom, Deck, & Waterways
Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors, No. of
Cables
Hawsers and Warps
Standing and Running Rigging

Committee's Minute _____ 18____
Character assigned _____
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) _____ Paid _____ 18____