

ANNUAL SURVEYS.

28227

(Received at London Office,

30/10/80

382

Survey held at Hamburg Date, first Survey 9th October, Last Survey 11th October, 18 80
 in on the Iron Ship "Olive" Master W. A. Weigel
 Book. 136 Tonnage 847 Built at Sunderland When built 1874 s.m.
 By whom built Pile Owners G. H. Hinrich
 Port belonging to Hamburg Destined Voyage Valparaiso
 If Surveyed Afloat or in Dry Dock In Wencke's Dry Dock

Last Survey, No. 26454 Port of Iron

Classed

Years assigned.

Character in Register Book.

100 A 1

Present Condition of the

Decks Good

Waterways do

Comings do

Upper Deck Beams & Fastenings do

Lower Deck Beams & Fastenings do

Planksheers do

Sheerstrakes do

Topsides do

Wales do

Plank (Bottom) and Counter Good

Engine Room Skylights Coal Bunker, Openings, Lids, &c.

General Observations, Opinion as to Class, &c.

Treenails Riveting Good

Breasthooks and Stemson do

Transoms, Pointers, and Crutches do

Timbers of the Frame at the Openings do

Ditto ditto at other places do

Keelsons do

Clamps and Shelves do

Ceiling do

Rudder do

Copper or Y.M. Patent Paint When put on Now

Caulking of Good

Bottom, Deck, & Waterways Good

Scuppers Good

Cargo and Main Hatchways Good

Hatches Good

Windlass and Capstan Good

Pumps do

Boats do

Masts, Yards, &c. do

Condition, how ascertained do

Sails do

Anchors, No. of Six do

Cables do

Hawsers and Warps do

Standing and Running Rigging do

Vessel placed in dry dock, bottom sighted and found in very good condition. She has been repainted all over and is in very good state. I am of the opinion her to have to remain in her character.

Committee's Minute

Tuesday, November, 2nd 1880.

Character assigned

TBW For change of Owners £1.0.0. Certificate (if required) 5/- Paid 28th October, 18 80

Surveyor to Lloyd's Register of British and Foreign Shipping.

No. Survey held at

Date, first Survey

Last Survey

18

No. in on the
Reg. Book.

Master

Tonnage Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M. When put on

Caulking of

Bottom, Deck, & Waterways

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Committee's Minute

18


Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18



© 2019

Lloyd's Register Foundation

IRON 496-0098