

ANNUAL SURVEYS.

No. 29820

Survey held at London

Date, first Survey 1st November

Last Survey 4th November

1880

No. in Reg. Book. 286

on the S. Carnarvon Castle

Master B. Backhouse

Tonnage 1165

Built at Glasgow

When built 1867-68

By whom built Barclay

Owners D. Currie & Co

Port belonging to London

Destined Voyage Algod Bay

If Surveyed Afloat or in Dry Dock

Greens dry dock

Last Survey, No. 24683

Port of Iron

Classed

Years assigned.

Character in Register Book.

* A 1 10.79
S.S. 2.79

Present Condition of the

Decks

Good

Treenails Rivets

Good

Waterways

do

Breasthooks and Stemson

do

Comings

do

Transoms, Pointers, and Crutches

do

Upper Deck Beams & Fastenings

do

Timbers of the Frame at the Openings

do

Lower Deck Beams & Fastenings

do

Ditto ditto at other places

do

Planksheers

do

Keelsons

do

Sheerstrakes

do

Clamps and Shelves

do

Topsides

do

Ceiling

do

Wales

do

Rudder

do

Plank (Bottom) and Counter

do

Copper or Y.M.

When put on

Caulking of Bottom, Deck, & Waterways

do

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated.
This vessel appears in good condition and eligible to remain as classed.
Surveyed with ballast in the main hold

Committee's Minute

Friday, November 19th. 1880

Thos. Bougdon

Character assigned

* A 1

TBW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No.

Survey held at London

Date, first Survey 1st Nov

Last Survey 2nd Nov

1880

No. in Reg. Book. 361

on the S. "Oxford"

Master Abbott

Tonnage 1200

Built at Sunderlands

When built 1869

By whom built Oswalds

Owners J. Currie, B. & Co

Port belonging to London

Destined Voyage Adelaide

If Surveyed Afloat or in Dry Dock

Greens dry dock

Last Survey, No. 23997

Port of Iron

Classed

Years assigned.

Character in Register Book.

* A 1 6.79
S.S. 2.78

Present Condition of the

Decks

Good

Treenails Rivets

Good

Waterways

do

Breasthooks and Stemson

do

Comings

do

Transoms, Pointers, and Crutches

do

Upper Deck Beams & Fastenings

do

Timbers of the Frame at the Openings

do

Lower Deck Beams & Fastenings

do

Ditto ditto at other places

do

Planksheers

do

Keelsons

do

Sheerstrakes

do

Clamps and Shelves

do

Topsides

do

Ceiling

do

Wales

do

Rudder

do

Plank (Bottom) and Counter

do

Copper or Y.M.

When put on

Caulking of Bottom, Deck, & Waterways

do

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated. Rudder pintles pushed. This vessel appears eligible to remain as classed.
Surveyed with ballast damaged over the main hold.

Committee's Minute

Friday, November 19th. 1880

Thos. Bougdon

Character assigned

* A 1

TBW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

IRON 496-0169

Carnegie Endowment

8

Oxford



© 2019

Lloyd's Register
Foundation