

ANNUAL SURVEYS.

284492

No. 4500 Survey held at West Hartlepool Date, first Survey _____ Last Survey 15th November 1880
 No. in on the Sea King Standard Master Jarnell
 Reg. Book. 995 Tonnage (1074 / 1576) Built at West Hartlepool When built 1875 - 7 mo
 By whom built Gray Owners W. Gray & Co
 Port belonging to West Hartlepool Destined Voyage Boston
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 27905 Port of Dun Classed S.S. Nil. No. 1-79 Years assigned. 100 A1 Character in Register Book. 9/00

Present Condition of the Decks Good Treenails Quite Good
 Waterways (Quite) Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers _____ Keelsons Good
 Sheerstrakes Good Clamps and Shelves _____
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Now done bottom cleaned down & coated with paint. Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion remain as now classed 100 A1

Committee's Minute Friday, November 19th. 1880
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping. S. P. Gladstone
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____

Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required) _____ Paid _____ 18 _____

