

ANNUAL SURVEYS.

(Received at London Office, 28473/80)

No. 15111 Survey held at South Shields Date, first Survey 15th Nov Last Survey 15th Nov 1880
on the S. S. "Elphinstone" Master J. Beale
Book. 1146 Tonnage 1776 Built at Newcastle When built 1874 - 3M
By whom built Palmer & Co. Owners Mac Intyre 13 1/2 %
Port belonging to Newcastle Destined Voyage Genoa
If Surveyed Afloat or in Dry Dock Under dry dock

Last Survey, No. 23661 Port of Irish

Classed

90A1

Present Condition of the
Decks

Good

Treenails

Rivets

Good

S. S. No. 1-77-5-79

Waterways

do

Breasthooks and Stemson

do

Windlass and Capstan

Good

Comings

do

Transoms, Pointers, and Crutches

do

Pumps

do

Upper Deck Beams & Fastenings

do

Timbers of the Frame at the Openings

do

Boats 4 in 19 1/2

do

Lower Deck Beams & Fastenings

do

Ditto ditto at other places

do

Masts, Yards, &c.

do

Planksheers

do

Keelsons

do

Condition, how ascertained from deck

do

Sheerstrakes

do

Clamps and Shelves

do

Sails Complete

do

Topsides

do

Ceiling

do

Anchors, No. of 2 1/2 1 1/2 2 1/2

do

Wales

do

Rudder

do

Cables part full

do

Plank (Bottom) and Counter

do

Copper or Y.M. Paint When put on now

Hawsers and Warps

do

Caulking of

do

Standing and Running Rigging

do

Bottom, Deck, & Waterways

Good

Cargo and Main Hatchways

do

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Hatches do

General Observations, Opinion as to Class, &c.

Vessel placed in dry dock bottom cleaned and rewater with paint -
She is now in good and efficient condition and in my opinion
eligible to remain as classed -

Committee's Minute

Friday, November 26th 1880

Character assigned

90A1

DRW

R. Williamson
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) ☒ Paid ☒ 18 ☒

No. 15111 Survey held at South Shields Date, first Survey 15th Nov Last Survey 15th Nov 1880
on the S. S. "Elphinstone" Master J. Beale
Reg. Book. 1146 Tonnage 1776 Built at Newcastle When built 1874 - 3M
By whom built Palmer & Co. Owners Mac Intyre 13 1/2 %
Port belonging to Newcastle Destined Voyage Genoa
If Surveyed Afloat or in Dry Dock Under dry dock

Last Survey, No. 23661Port of Irish

Classed

Years assigned.

Character in Register Book.

Present Condition of the
Decks

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Plank (Bottom) and Counter

Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) ☒Paid ☒18 ☒