

REPORT of SURVEY for REPAIRS, &c.

No. 3975

No. in Survey held at Reg. Book.

Bristol

Date, first Survey 20 Nov-88 Last Survey 22 November 1888

358 on the Scio St. Heptarchy

Master J. Prethorne

TONNAGE under Tonnage Deck 703

Ditto of Spar Deck, or Avoing Deck

Ditto of Poop

Ditto of Raised Or. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage 780

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St' mer, cut on Bm. 502

Built at London

When built 1871 8

Owners J. Bacon

Port belonging to London

Residence

By whom built Samuda

Destined Voyage Sardinia

If Surveyed Afloat or in Dry Dock

Stotherts Dry Dock

(State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

Years assigned.

Character in Register Book.

Last Survey, No. 28330 Port Iron

Classed 95 A 1

REPAIRS, OR EXAMINATION AS PER RULE on account of damage Cause of Repairs to be clearly stated.

S.S. Liv. No. 76. 9.80
S.S. Liv. No 2-80

Vessel placed in dry dock and surveyed on account of damage sustained through striking the ground in the River Avon. Some rubbed plates of bottom cleaned and painted. A portion of shoe plate at lower part of stem renewed - together with about two dozen rivets in the stem.

The Master states that the vessel has very recently undergone S.S. No 2 at Liverpool.

Present Condition of the

Decks	Good	Greenails Rivets	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	From deck
Planksheers	"	Keelsons	"	Sails	Good
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of	3B 15 2K
Topsides	"	Ceiling	"	Cables	part seen. Good
Wales	"	Rudder	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper (or Iron) Cement When put on	71	Standing & Running Rigging	"
Engine Room Skylights	Good	Caulking of			
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good		
Scuppers	"			Cargo and Main Hatchways	Hatches

General Observations, Opinion as to Class, &c.

She is now in a good and efficient condition and is eligible in my opinion to remain as classed

The Amount of Entry Fee ... £ : : received by me, Ry.

Special ... £ 3 : 3 : 23 Nov 1888

Certificate (if required)

to be sent as per margin... £ : :

(Travelling Expenses, if any, £)

Committee's Minute

Friday, November 26th 1888

Character assigned

95 A 1

L. Hearle
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation