

# ANNUAL SURVEYS.

28492

No. 29724 Survey held at London Date, first Survey Sept 30<sup>th</sup> Last Survey Oct 14 1880  
 No. in on the S Lady Cairns Master A Carnell  
 Reg. Book. 58 Tonnage 1265 Built at Belfast When built 1865 4  
 By whom built Harland Owners British Ship Owners Co  
 Port belonging to Belfast ? Liv. Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Blackwall point Dry Dock

Last Survey, No. 24172 Port of Iron  
 Present Condition of the  
 Decks Good Treenails Pivots Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom be coated.

Classed A 1 8.75  
 Years assigned. SS Lon M.R. 17.  
 Character in Register Book.

*She is now in good condition and eligible to remain as classed.*

Committee's Minute Tuesday, October, 19th 1880.

Character assigned A 1 T.B.W.

Senhouse Martinade  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 1036 Survey held at London Date, first Survey Oct 6<sup>th</sup> Last Survey Oct 13<sup>th</sup> 1880  
 No. in on the S Star of France Master E Hughes  
 Reg. Book. 1036 Tonnage 7565 Built at Belfast When built 1877 11  
 By whom built Harland Owners J Barry & Co  
 Port belonging to Belfast Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 22098 Port of Iron  
 Present Condition of the  
 Decks Good Treenails Pivots Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom be coated.

Classed A 1 10.75  
 Years assigned. SS Lon M.R. 17.  
 Character in Register Book.

*She is now in good condition and eligible to remain as classed.*

Committee's Minute Tuesday, October, 19th 1880.

Character assigned 100 T.B.W.

Senhouse Martinade  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18



