

ANNUAL SURVEYS.

No. 29724 Survey held at London Date, first Survey Sept 30th Last Survey Oct 14 1880
 No. in on the S Lady Cairns Master A. Carnell
 Reg. Book. 58 Tonnage 1265 Built at Belfast When built 1865 4
 By whom built Harland Owners British Ship Owners Co
 Port belonging to Belfast? Liv. Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Blackwall point Dry Dock

Last Survey, No. 24172 Port of Iron Classed A 1. 8. 75
 Present Condition of the Decks Good Treenails Pivots Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom be coated.

She is now in good condition and eligible to remain as classed.

Committee's Minute Tuesday, October, 19th 1880.

Character assigned A 1

Senhouse Martinade

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. 1036 Survey held at London Date, first Survey Oct 6th Last Survey Oct 13th 1880
 No. in on the S Star of France Master E. Hughes
 Reg. Book. 1036 Tonnage 7565 Built at Belfast When built 1877 11
 By whom built Harland Owners J. Barry & Co.
 Port belonging to Belfast Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 22098 Port of Iron Classed A 1. 10. 78
 Present Condition of the Decks Good Treenails Pivots Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom be coated.

She is now in good condition and eligible to remain as classed.

Committee's Minute Tuesday, October, 19th 1880.

Character assigned 100

Senhouse Martinade

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

Lloyd's Register
Foundation