

ANNUAL SURVEYS. 28591


No. 39860 Survey held at London Date, first Survey Nov 15 Last Survey Nov 27 1880
 No. in on the SS Perin Master J Scott
 Reg. Book. 298 Tonnage 1016 Built at Glasgow When built 1877-4
1234 By whom built London & Glasgow Co Owners R. W. Cousens & Co.
 Port belonging to London Destined Voyage, India
 If Surveyed Afloat or in Dry Dock Pontoon, Victoria Dock

Last Survey, No. 25409 Port of Iron Classed 100 A-1.80.
 Present Condition of the Decks good Treenails Rivets good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan good
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "
 Planksheers " Keelsons " Masts, Yards, &c. "
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained From St
 Topsides " Ceiling " Sails good
 Wales " Rudder " Anchors, No. of 3 No. 12 & Kedges
 Plank (Bottom) and Counter " Copper or Y.M. Coutie When put on new Cables Part on deck good
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c. owing to damage several bolts & seams at both ends of the vessel caulked.
She is now in good repair and eligible to remain as classed.
Damage see £220.

Committee's Minute Friday, December 3rd. 1880. Senhouse Martindale
 Character assigned 100 A-1 JTBW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 Last Survey, No. Port of Classed
 Present Condition of the Decks Treenails
 Waterways Breasthooks and Stemson Windlass and Capstan
 Comings Transoms, Pointers, and Crutches Pumps
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings Boats
 Lower Deck Beams & Fastenings Ditto ditto at other places Masts, Yards, &c.
 Planksheers Keelsons Condition, how ascertained
 Sheerstrakes Clamps and Shelves Sails
 Topsides Ceiling Anchors, No. of
 Wales Rudder Cables
 Plank (Bottom) and Counter Copper or Y.M. When put on Hawasers and Warps
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18



IRON 497-019