

# ANNUAL SURVEYS. 28665

Survey held at London. Date, first Survey 9<sup>th</sup> Dec Last Survey 13<sup>th</sup> Dec 1880  
No. in on the Iron S. "Sea Queen" Master J. Thurston  
Reg. Book. 273 Tonnage 746 Built at Glasgow When built 1858  
By whom built Stephen Owners J. H. Allan  
Port belonging to London Destined Voyage Cardiff, then to India  
If Surveyed Afloat or in Dry Dock In the Poplar Dry Dock

Last Survey, No. 2834 Port of Iron Classed S.S. Lon N<sup>o</sup> 3-69 Years assigned. 10.79 Character in Register Book. A. 1  
Present Condition of the  
Decks good Treenails rivets good S.S. Lon N<sup>o</sup> 2-78  
Waterways D<sup>o</sup> Breasthooks and Stemson D<sup>o</sup>  
Comings D<sup>o</sup> Transoms, Pointers, and Crutches D<sup>o</sup>  
Upper Deck Beams & Fastenings D<sup>o</sup> Timbers of the Frame at the Openings D<sup>o</sup>  
Lower Deck Beams & Fastenings D<sup>o</sup> Ditto ditto at other places D<sup>o</sup>  
Planksheers D<sup>o</sup> Keelsons D<sup>o</sup>  
Sheerstrakes D<sup>o</sup> Clamps and Shelves D<sup>o</sup>  
Topsides D<sup>o</sup> Ceiling D<sup>o</sup>  
Wales D<sup>o</sup> Rudder D<sup>o</sup>  
Plating (Bottom) and Counter D<sup>o</sup> Copper or Y.M. When put on  
Caulking of Bottom, Deck, & Waterways good  
Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good  
General Observations, Opinion as to Class, &c. The bottom has been examined, cleaned and coated.  
Vessel surveyed with ballast in the hold amidships & a quantity of kentledge aft.  
A bower anchor has been supplied in the place of one stated to have been lost.  
From the certificate - weight of new anchor ex. stock 26 - 8 - 14 - proof strain 25 - 14 - 1 - 14 -  
E. R. Litch Superintendent Tipton 18<sup>th</sup> Oct<sup>r</sup> 1880.  
This vessel appears to be in good and efficient condition & eligible to remain as classed.  
Committee's Minute Friday, December 31<sup>st</sup> 1880. J. H. Truscott.  
Character assigned JBW Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) Paid 18

No.            Survey held at            Date, first Survey            Last Survey            18            
No. in on the            Master             
Reg. Book.            Tonnage            Built at            When built             
By whom built            Owners             
Port belonging to            Destined Voyage             
If Surveyed Afloat or in Dry Dock           

Last Survey, No.            Port of            Classed            Years assigned.            Character in Register Book.             
Present Condition of the  
Decks            Treenails             
Waterways            Breasthooks and Stemson             
Comings            Transoms, Pointers, and Crutches             
Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings             
Lower Deck Beams & Fastenings            Ditto ditto at other places             
Planksheers            Keelsons             
Sheerstrakes            Clamps and Shelves             
Topsides            Ceiling             
Wales            Rudder             
Plank (Bottom) and Counter            Copper or Y.M.            When put on             
Caulking of Bottom, Deck, & Waterways             
Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers            Cargo and Main Hatchways            Hatches             
General Observations, Opinion as to Class, &c.           

Committee's Minute            18            
Character assigned            Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required)            Paid            18