

ANNUAL SURVEYS.

No. 29932 Survey held at London Date, first Survey Dec 13th Last Survey Dec 16th 1880
 No. in on the SS Antonio Master Seaborn
 Reg. Book. 1082 Tonnage 124 Built at Sunderland When built 1877 6
 By whom built Saxford Owners Str Nav & West
 Port belonging to London Destined Voyage Cardiff Singapore
 If Surveyed Afloat or in Dry Dock Thames Iron Works Ltd

Last Survey, No. 26995 Port of Iron Classed 100A 6.80.
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Crated When put on New
 Caulking of "
 Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom & counter & new capeller.

*She is now in an efficient state
and eligible to remain as classed.*

Committee's Minute Tuesday, December, 28th 1880.
 Character assigned 100A Seaborn Martin
Note withdrawn DTBW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) " Paid " 18"

No. 29932 Survey held at London Date, first Survey " Last Survey " 18"
 on the " Master "
 Reg. Book. " Tonnage " Built at " When built "
 By whom built " Owners "
 Port belonging to " Destined Voyage "
 If Surveyed Afloat or in Dry Dock "

Last Survey, No. " Port of " Classed "
 Present Condition of the
 Decks " Treenails "
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. " When put on "
 Caulking of "
 Bottom, Deck, & Waterways "
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers " Cargo and Main Hatchways " Hatches "
 General Observations, Opinion as to Class, &c. "

Committee's Minute " 18"
 Character assigned " Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) " Paid " 18"