

# ANNUAL SURVEYS.

28734  
Received at London Office, 25<sup>th</sup> Dec 1880

No. 4912 Survey held at Greenock Date, first Survey 5<sup>th</sup> Dec Last Survey 4<sup>th</sup> December 1880  
 No. in on the Sw S.S. "Ella" Master V. J. Harrison  
Book. Tonnage 276 Built at Stockton When built 1878 - 2 No  
40 382 By whom built Richardson Owners J. M. Leonard & Son  
 Port belonging to Middlesbrough Destined Voyage Seville  
 If Surveyed Afloat or in Dry Dock Caird's Dry dock

Last Survey, No. 2346 Port of Swansea Iron Classed 100A.1  
Years assigned. 6-49  
Character in Register Book.

Present Condition of the <u>good when seen</u>	<u>Trunnels</u> <u>good</u>	
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Windlass and Capstan <u>good</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Pumps <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings <u>do</u>	Boats <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	<u>Ditto</u> ditto at other places <u>do</u>	Masts, Yards, &c. <u>do</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Condition, how ascertained <u>See from deck</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Sails <u>Sufficient</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Anchors, No. of <u>do</u>
Wales <u>do</u>	Rudder <u>do</u>	Cables <u>do</u>
Plank (Bottom) and Counter <u>do</u>	Copper or Y.M. <u>When put on</u>	Hawsers and Warps <u>do</u>
Engine Room Skylights <u>good</u>	Caulking of <u>good when seen</u>	Standing and Running Rigging <u>do</u>
Coal Bunker, Openings, Lids, &c. <u>good</u>	Bottom, Deck, & Waterways <u>seen</u>	

General Observations, Opinion as to Class, &c. This vessel had touched the ground and was put into dock on sight the bottom. The Rudder Steps and the bottom plank have been renewed and the bottom has now been scraped and painted. She appears to be in good and efficient condition and desirable, in my opinion, to remain as classed.

Committee's Minute Friday, December 31st. 1880.  
 Character assigned 100A.1  
R. Reed.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Special Dec 31<sup>st</sup> 1880 Paid 25 Dec 1880

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18  
 No. in on the \_\_\_\_\_ Master \_\_\_\_\_  
Book. Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
Years assigned. \_\_\_\_\_  
Character in Register Book. \_\_\_\_\_

Present Condition of the _____	<u>Treenails</u> _____	
Decks _____	Breasthooks and Stemson _____	Windlass and Capstan _____
Waterways _____	Transoms, Pointers, and Crutches _____	Pumps _____
Comings _____	Timbers of the Frame at the Openings _____	Boats _____
Upper Deck Beams & Fastenings _____	Ditto ditto at other places _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Condition, how ascertained _____
Planksheers _____	Clamps and Shelves _____	Sails _____
Sheerstrakes _____	Ceiling _____	Anchors, No. of _____
Topsides _____	Rudder _____	Cables _____
Wales _____	Copper or Y.M. _____ When put on _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Caulking of _____	Standing and Running Rigging _____
Engine Room Skylights _____	Bottom, Deck, & Waterways _____	
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Cargo and Main Hatchways _____
Hatches _____		

General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

IRON 47-0305