

ANNUAL SURVEYS.

No. 2992 Survey held at London Date, first Survey 20th Dec. Last Survey 21st Dec 1880
 No. in on the Iron S.S. "Eclipse" Master G. Palmer
 Reg. Book. 122 Tonnage 1304 Built at Stockton When built 1877
 By whom built Pearse Owners V. Appleby & Co.
 Port belonging to W. Hartlepool Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Regent Dry Dock

Last Survey, No. 2593 Port of Iron Classed 100 A 1
 Years assigned. 3. 30
 Character in Register Book.
 Present Condition of the
 Decks Good Treennails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes Plating Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coating When put on Iron
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers " Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c.


The bottom has been cleaned & coated, she is in good condition and eligible in my opinion, to continue as classed

Committee's Minute Friday, December 24th 1880
 Character assigned 100 A 1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRM Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Years assigned.
 Character in Register Book.
 Present Condition of the
 Decks Treennails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18



1880-4497-0308