

ANNUAL SURVEYS.

28758

(Received at London Office, 22/12/80)

No. 29903 Survey held at London Date, first Survey 7 Dec 80 Last Survey 18 Dec 80 1880
 No. in on the S.S. Glenartney Master Auld
 Reg. Book. 431 Tonnage 1400 Built at Glasgow When built 1873 qm
 By whom built W & G's Co Owners W & G's Co
 Port belonging to Glasgow Destined Voyage India
 If Surveyed Afloat or in Dry Dock Popular dry dock

Last Survey, No. 27388 Port of Iron Classed 100A1 8-80 Years assigned 5.5-4-1-78 Character in Register Book.
 Present Condition of the Decks Good Treenails Reinets Good
 Waterways do Breasthooks and Stenson do Windlass and Capstan Good
 Comings do Transoms, Pointers, and Crutches do Pumps do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Boats do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Masts, Yards, &c. do
 Planksheers do Keelsons do Condition, how ascertained from deck
 Sheerstrakes do Clamps and Shelves do Sails well found
 Topsides do Ceiling do Anchors, No. of 25. 1 P & 2 Wedges
 Wales do Rudder do Cables complete
 Plank (Bottom) and Counter do Copper or Y.M. - When put on - Hawasers and Warps sufficient
 Engine Room Skylights do Caulking of Bottom, Deck, & Waterways do Standing and Running Rigging good
 Coal Bunker, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways do Hatches do
 General Observations, Opinion as to Class, &c.


Bottom cleaned and recoated. This vessel appears eligible to remain as classed.

Committee's Minute Tuesday, December, 21st 1880. W. B. Douglas
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) --- Paid --- 18---

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned _____ Character in Register Book.
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stenson _____ Windlass and Capstan _____
 Comings _____ Transoms, Pointers, and Crutches _____ Pumps _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Boats _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Masts, Yards, &c. _____
 Planksheers _____ Keelsons _____ Condition, how ascertained _____
 Sheerstrakes _____ Clamps and Shelves _____ Sails _____
 Topsides _____ Ceiling _____ Anchors, No. of _____
 Wales _____ Rudder _____ Cables _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____ Hawasers and Warps _____
 Engine Room Skylights _____ Caulking of Bottom, Deck, & Waterways _____ Standing and Running Rigging _____
 Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18____



IRON497-0341

ANNUAL SURVEYS

[Faint, illegible handwritten text, likely bleed-through from the reverse side of the page.]

Memorandum



© 2019

Lloyd's Register
Foundation