

ANNUAL SURVEYS.

28759

No. 39314 Survey held at Londonderry Date, first Survey 1 Dec^r Last Survey 7 Dec^r 1880
 No. in on the S.S. Glendale Master James
 Reg. Book. 449 Tonnage 727 Built at W. Hartlepool When built 1874
 By whom built Ironie Owners Steel Young & Co
 Port belonging to W. Hpl Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Rough dry dock

Last Survey, No. 25734 Port of IronPresent Condition of the
Decks

Waterways	<u>Good</u>	Treenails	<u>Pinets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Comings	<u>de</u>	Breasthooks and Stemson	<u>de</u>	<u>de</u>	Pumps	<u>de</u>
Upper Deck Beams & Fastenings	<u>de</u>	Transoms, Pointers, and Crutches	<u>de</u>	<u>de</u>	Boats	<u>four</u>
Lower Deck Beams & Fastenings	<u>de</u>	Timbers of the Frame at the Openings	<u>de</u>	<u>de</u>	Masts, Yards, &c.	<u>de</u>
Planksheers	<u>de</u>	Ditto ditto at other places	<u>de</u>	<u>de</u>	Condition, how ascertained	<u>from deck</u>
Sheerstrakes	<u>de</u>	Keelsons	<u>de</u>	<u>de</u>	Sails	<u>well found</u>
Topsides	<u>de</u>	Clamps and Shelves	<u>de</u>	<u>de</u>	Anchors, No. of	<u>315. 1 S & 2 Hedges</u>
Wales	<u>de</u>	Ceiling	<u>de</u>	<u>de</u>	Cables	<u>complete</u>
Plank (Bottom) and Counter	<u>de</u>	Rudder	<u>de</u>	<u>de</u>	Hawsers and Warps	<u>sufficient</u>
Engine Room Skylights	<u>de</u>	Copper or Y.M.	<u>-</u>	When put on	Standing and Running Rigging	<u>good</u>
Coal Bunker, Openings, Lids, &c.	<u>de</u>	Caulking of	<u>de</u>	<u>de</u>	Cargo and Main Hatchways	<u>de</u>
General Observations, Opinion as to Class, &c.	<u>de</u>	Bottom, Deck, & Waterways	<u>de</u>	<u>de</u>	Hatches	<u>de</u>

Bottom cleaned and recoated. Rudder pintles
lashed. Iron Rail partly renewed. This vessel appears
eligible to remain as classed.

Committee's Minute Tuesday, December, 24th 1880.

Character assigned

T.B.W. 9021

Thos. Longdon
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the

No. of Report

No. in Register Book

Double bottom, aft, length 64

Double bottom, under engines and

Double bottom, constructed on 1

Fore peak tank, water capacity

Midship deep tank

Plank (Bottom) and Counter

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M. When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Cargo and Main Hatchways Hatches Committee's Minute 18 Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

Memorandum