

ANNUAL SURVEYS.

28783
(Received at London Office, Dec 13th 1880)

No. 39884 Survey held at London Date, first Survey Dec 4th 1880 Last Survey 4th Dec 1880
 No. in on the Reg. Book. 37 on the Swedish Kingdom of Sweden Master W. L. Smith
 Tonnage 88.8 1/2 Built at Sunderland When built 1875 - 4 mo
 By whom built Mouney Owners Gosman & Smith
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Bullhead dry dock & afloat


Last Survey, No. 23195 Port of London Classed 100A 1 4-79
Years assigned. Character in Register Book.
 Present Condition of the Decks Good Treenails Good Rivets Good
 Waterways --- Breasthooks and Stemson ---
 Comings --- Transoms, Pointers, and Crutches ---
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings ---
 Lower Deck Beams & Fastenings --- Ditto ditto at other places ---
 Plank sheers --- Keelsons ---
 Sheerstrakes --- Clamps and Shelves ---
 Topsides --- Ceiling ---
 Wales --- Rudder ---
 Plank (Bottom) and Counter --- Copper or Y.M. plumet When put on 1875
 Engine Room Skylights --- Coal Bunker, Openings, Lids, &c. --- Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom repainted. She is now in good condition and in my opinion eligible to continue as classed

Committee's Minute Tuesday, December, 14th 1880.
 Character assigned 100A 1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) --- Paid --- 18 ---

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18
 No. in on the _____ Reg. Book. _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Plank sheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



IRON 497-0376