

ANNUAL SURVEYS.

No. 4535 Survey held at West Hartlepool Date, first Survey 1871 Last Survey 1880
No. in on the 501 Reg. Book. 501 Tonnage 1547 Built at West Hartlepool When built 1871 4 mo
By whom built Deaton Owners Johnston & Sons
Port belonging to Montrose Destined Voyage Copenhagen
If Surveyed Afloat or in Dry Dock In Dry Dock

(Received at London Office, 25/12/80)Last Survey 1880Last Survey, No. 26108 Port of Leam

Classed

Years assigned.

Character in Register Book.

90 A1

Present Condition of the

Decks GoodWaterways (Gutter) GoodComings GoodUpper Deck Beams & Fastenings GoodLower Deck Beams & Fastenings Good

Planksheers

Sheerstrakes GoodTopsides GoodWales GoodPlank (Bottom) and Counter GoodEngine Room Skylights Good

General Observations, Opinion as to Class, &c.

Treenails GoodBreasthooks and Stemson GoodTransoms, Pointers, and Crutches GoodTimbers of the Frame at the Openings GoodDitto ditto at other places GoodKeelsons Good

Clamps and Shelves

Ceiling GoodRudder Good

Copper or Y.M. When put on

Caulking of Bottom, Deck, & Waterways GoodWindlass and Capstan GoodPumps 2 - GoodBoats 4 - GoodMasts, Yards, &c. GoodCondition, how ascertained From DeckSails GoodAnchors, No. of 3 Bowers / Stream 2 RedCables GoodHawsers and Warps 9 1/2 - 8 1/2 - 8 1/2 - 8 1/4 - 7 1/4 - 5 1/2 GoodStanding and Running Rigging GoodCoal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

Is now in a good & efficient state, fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion remain as now classed 90 A1
S.L. H.L. No. 2-79

Committee's Minute

Tuesday, December, 21st 1880.

Character assigned

90 A1STBS. M. Gladstone

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) in Paid in 1880

No. Survey held at Date, first Survey Last Survey 18
No. in on the Reg. Book. Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M. When put on

Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Cargo and Main Hatchways Hatches

Committee's Minute

18


Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18



© 2019

Lloyd's Register Foundation

TROW497-0402