


ANNUAL SURVEYS.

28826

(Received at London Office,

No. 29929 Survey held at London Date, first Survey 13th Dec^r Last Survey 16th Dec^r 1880
 No. in on the Iron Ste. Sr. "Petrarch" Master R. John.
 Reg. Book. 361. Tonnage 1297 Built at S. Shields. When built 1877-9 mo.
1444 By whom built Readhead. Owners M. Andrew & Co.
 Port belonging to London Destined Voyage Hamburg.
 If Surveyed Afloat or in Dry Dock In Millwall Dry Dock.



Last Survey, No. 23008 Port of Iron Classed _____ Years assigned. _____ Character in Register Book. 100 A. 1.
3.79

Present Condition of the Decks <u>good</u>	Treenails <u>rivets</u> <u>good</u>	
Waterways <u>D^o</u>	Breasthooks and Stenson <u>D^o</u>	Windlass and Capstan <u>good</u>
Comings <u>D^o</u>	Transoms, Pointers, and Crutches <u>D^o</u>	Pumps <u>D^o</u>
Upper Deck Beams & Fastenings <u>D^o</u>	Timbers of the Frame at the Openings <u>D^o</u>	Boats <u>D^o</u>
Lower Deck Beams & Fastenings <u>D^o</u>	Ditto ditto at other places <u>D^o</u>	Masts, Yards, &c. <u>D^o</u>
Planksheers <u>D^o</u>	Keelsons <u>D^o</u>	Condition, how ascertained <u>from the deck</u>
Sheerstrakes <u>D^o</u>	Clamps and Shelves <u>D^o</u>	Sails <u>good</u>
Topsides <u>D^o</u>	Ceiling <u>D^o</u>	Anchors, No. of <u>4 No. 15. 2K.</u>
Wales <u>D^o</u>	Rudder <u>D^o</u>	Cables <u>complete</u>
Plating (Bottom) and Counter <u>D^o</u>	Copper or Y.M. <u>When put on</u>	Hawsers and Warps <u>sufficient</u>
Engine Room Skylights <u>good</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	Standing and Running Rigging <u>good</u>
Coal Bunker, Openings, Lids, &c. <u>good</u>	Scuppers <u>good</u>	Cargo and Main Hatchways <u>good</u>
Hatches <u>good</u>		

General Observations, Opinion as to Class, &c.
The bottom has been examined, cleaned & coated.
Vessel surveyed with ballast in the holds all fore & aft.
She appears to be in good and efficient condition and eligible to remain as classed.

Committee's Minute Friday, December 31st. 1880. J. A. Truscott.
 Character assigned 100 A. 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Water _____	Breasthooks and Stenson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Cargo and Main Hatchways _____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Hatches _____

General Observations, Opinion as to Class, &c.
 Committee's Minute _____ 18 _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



TRON 047-0433