

ANNUAL SURVEYS.

28884

No. 39903 Survey held at London Date, first Survey and Last Survey 16. 17. 83
 No. in on the C. Erato Master Chas. Elliott
 Reg. Book. 22 Tonnage 1205 Built at Isle of Man When built 1864
 By whom built Ramsay S. B. Co. Owners J. Lidgett & Sons
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock Carter's Dry Dock

Last Survey, No. 2506 Port of Iron Classified S. S. Cl. No 3-79 11.79

Present Condition of the
 Decks Good Freemantle Ports Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes Plating " Clamps and Shelves "
 Topsides " " Ceiling "
 Wales " " Rudder lifted & painted & bushed
 Plank (Bottom) and Counter " " Copper or Y.M. Coating When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers " Cargo and Main Hatchways Good Hatches "

General Observations, Opinion as to Class, &c.
She has now been supplied with 1 new boat; New Fore Top Gall Mast & Mizen Topsail yard - she is in good condition & eligible in my opinion, to continue as classed

Committee's Minute 18
 Character assigned James Surpin
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) PAID 18

No. 234 Survey held at London Date, first Survey and Last Survey Nov-24. 1880
 No. in on the C. Westland Master Thos. Moffatt
 Reg. Book. 1116 Tonnage 1185 Built at Port Glasgow When built 1878
 By whom built Duncan Owners Albion S. Co.
 Port belonging to Glasgow Destined Voyage Otago
 If Surveyed Afloat or in Dry Dock Regent Dry Dock

Last Survey, No. 25725 Port of Iron Classified 100 A 1 11.79

Present Condition of the
 Decks Good Freemantle Ports Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes Plating " Clamps and Shelves "
 Topsides " " Ceiling "
 Wales " " Rudder "
 Plank (Bottom) and Counter " " Copper or Y.M. Coating When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers " Cargo and Main Hatchways Good Hatches "

General Observations, Opinion as to Class, &c.
She has now had a New Main Top Gall Yard, she is in good condition and eligible, in my opinion, to continue as classed

Committee's Minute Friday, December 17th. 1880.
 Character assigned 100 A 1
James Surpin
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) PAID 18