


4-3-78
 14/3/78

L.L. 'Ammandale'
 Repair No. 4061

No 75
 1/4" = 1' foot
 Rev 2/3/78 & 13/3/78
 B

2006
 20/2/78



14/3/78
 14/3/78

W-0

56
 38
 21 2

1779
 20/2/78

Edw. Wilby & Co.
 p. Henry Wilby

75

Iron
No 21806

7
2.3.7
8

IRON 530-0026



© 2021

Lloyd's Register
Foundation