

Her Masts, Yards, &c. are in Good condition, and sufficient in size and length.

She has SAILS.			CABLES, &c.		ANCHORS, and their weights.		
N ^o .		Fathoms.		Inches.	N ^o .		
2	Fore Sails,	300	Chain	1 1/4	3	Bower,	36-12-0-36-0-0-36-0-0
1	Fore Top Sails,	65	Hempen Stream Cable	9	1	Stream,	
2	Fore Topmast Stay Sails,	65	Hawser	8	2	Kedge,	
1	Main Sails,		Towlines				
2	Main Top Sails,	75	Warp	4			
and <u>well found in other</u>			All of <u>Good</u> quality.				
			<u>Sails</u>				

Her Standing and Running Rigging Keen sufficient in size and Good in quality.

She has one Long Boat and three others

The present state of the Windlass is Good Capstan Good and Rudder Good

General Remarks—Statement and Date of Repairs.

Listings have been left out in accordance with the Rules for the inspection of the condition of the hull which together with the other
when
been
been

LIN579-0186

EAST JARROW
HIVE IRON WORKS.
BY GATESHEAD
HYDRAULIC MACHINE FOR PROVING CHAIN CABLES.
This is to certify that I have this 15th day of
April 1844, **PROVED** for the "Sutton"
Burthen ¹⁰⁷⁵/₁₁₂₈ Tons Register Capt. W. D. Walker
100 Fathoms of ^{1 1/2}/₁₆ Inch Chain equal to 18
Inch Rope Manufactured by **THOS. ADDISON & SONS**
and numbered 901 Inspector for E. Moore
W. E. Munn

If Sheathed, Doubled, Felted, or Coppered Single bottom When last done

I am of opinion this Vessel should be Classed 4 A 1

The Amount of the Fee.....£ 5 : 2 : 3 is received by me, W. E. Munn

Special£ 1 : 2 : 3

Certificate (if required)£ : :

Committee's Minute 3rd Decr 1844

Character assigned A 1 for 4 years
W. E. Munn
X



© 2019
Lloyd's Register
Foundation

Her Masts, Yards, &c. are in Good condition, and sufficient in size and length.

She has SAILS.			CABLES, &c.		ANCHORS, and their weights.		
N ^o .		Fathoms.		Inches.	N ^o .		
2	Fore Sails,	300	Chain	1 1/4	3	Bower,	35-12-0-36-0-0-38-0-0
1	Fore Top Sails,	65	Hempen Stream Cable	9	1	Stream,	
2	Fore Topmast Stay Sails,	65	Hawser	8	2	Kedge,	
1	Main Sails,		Towlines				
2	Main Top Sails,	75	Warp	4			
and <u>well found in other</u>			All of <u>Good</u> quality.				
			<u>Sails</u>				


Her Standing and Running Rigging Good sufficient in size and Good in quality.

She has one Long Boat and three other

The present state of the Windlass is Good Capstan Good and Rudder Good

General Remarks—Statement and Date of Repairs.

Listings have been left out in accordance with the Rules for the inspection of the ship and the crew, which together with the other when been seen.



If Sheathed, Doubled, Felted, or Coppered single bottom When last done

I am of opinion this Vessel should be Classed 4 A 1

The Amount of the Fee.....£ 5-3 is received by me, W. H. P.

Special£ 1-2-3

Certificate (if required)£ : :

Committee's Minute 3rd Decr 1847

Character assigned A 1 for 4 E
AL