

321

Y. A.

By whom built Tulvey Where built Chester When built 1827

Destined Voyage *Liverpool*

Surveyed after

Decks.

Builder's Name _____

Surveyor's Name _____

Sails.

Owner's Name _____ © 2021

Nautical Surveyor's Name *Wm. A. B. B. B.*

SURVEYOR'S REMARKS.

Timbering.

The Quality,
Squaring, and
Workmanship.

*British oak, good quality and workmanship
Well squared*

Planking.

Outside and Inside
Quality, Edging,
and Workmanship.

British Oak

*Good quality and workmanship
both inside and outside*

Fastenings.

If Sheathed,
Doubled, or
Felted.

*Copper, Hasars hold beams, the deck beams secured
with double bedding oak bines, four inch stringer
and clamp the bilge and one timber stake,
copper butt bolts clinched, the breast hooks and
transoms dry and sound*

Repairs.

*Is now having her decks and waterways caulked
and was caulked outside and general overhauled in
1833*

General Observations
and Opinion as
required by the
Instructions.

*The general appearance favorable being in a
high state of repair and efficiency and should in
my opinion remain in the first description of the
First Class Twelve Years -*

The Amount of the Fee, "£

: 10 : 6 is received by me.

Widdleton

Committee Minute

13 August

1834

Character assigned

A + for 11 Years

W. C. Sturges



© 2021

Lloyd's Register
Foundation